SURVEY & REMONUMENTATION

MAR 2 1 1997

COMMISSION

APPROVED

Private Claims

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN CALHOUN COUNTY

For Corner In End of All CIN.			Fi	iing nequin	ement of Act /4, Mich. P.A. 19	RELORDED
Calhoun Clarence Twp.		Located In:		Corner Code :##	18 DCT 96 2:28 P.M.	
1.	Public Land Survey		т 1S Т	R 4W R	<u>M-1</u>	AWNE B. KORLANDER CLERK - R EGISTER OF DEEDS
			T T	R R		LIBER 1893 PAGE 300
2.	Property Controlling in Section	s s	T T	R R	L10EN ±	TITEL # MAR LHOE FAMA
3.	Miscellaneous	S	T T	R		Register of Deeds Stamp & File Number
	Property in Sec.	S	1	_ R		
4.	Lot No,	Recorded	d Plat			

, in a field survey on November 10 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Post set by Lucius Lyon, Deputy Surveyor, February 1825.

Perpetuation by James Gifford, L.S. in 1889, for the Northeast corner of Section 1,

Clarence Township, Calhoun County. Set a $2\frac{1}{2}$ " tile at the South side of a large stone that was placed using original bearing trees.

Perpetuation by Consumers Power Co. from map dated 1967. Found large stone, flat on bottom, chiseled cross on top for point.

P.A. 74, recorded by Alan Scheppelman, LS # 35998, on LCRC, dated Oct. 11, 1994, Liber 4, pg. 292, Jackson Co Records. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a large stone, with "X" cut on top, 3" below gravel surface, with bottom 6" of a $2\frac{1}{2}$ " Fireclay (tile) on the South side. The $2\frac{1}{2}$ " Fireclay was inside a hollow tile, which broke into many small pieces wheremoved.

Backhoe excavation of a 6' x 6' x 4' deep area to find stone and reset to 4' below surface. Set $2\frac{1}{2}$ " Fireclay and broken tile on top of stone.

Accepted stone as a careful and faithful perpetuation of the position of the original corner as remonumented by Gifford in 1889.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-1, T1S, R3W Corner is a cast iron, Harrison monument which is the standard monument for Calhoun County. Harrison monument is 4" x 30". MICHANIAN MANAGER STATE OF MICHIGAN S 22°-30' E 22" Hickory 69.651 40d & washer on West side S 80° E Double 12" Oak 51.97' 40d & washer on North side S 85° W DONALD J. 16" Hickory 60.731 40d & washer on North side 10" Hickory DAVIS N 15° E 119.34' PROFESSIONAL MANAGEMENT OF THE 40d & washer on West side 24" Hickory 14" Cherry 5° E 257.60' N 40d & washer on West side 49.00 West 40d & washer on North side 2" Hickory N 35° W 44.14' no nail East Steel post with survey marker sign attached, 24.5'. ALLO October 10, 1996 Signed by HATHER X Donald J. Dayis Surveyor's Michigan License (Ng. Date ___ 17617