1993

COMMISSION

For corners in

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

UGT.	6	ÿ	47	AM	193
		_			1

RECORDED

Filing Requirement of Act 74, Mich. P.A. 1970

CLERK REGISTER
CALHOUN COUNTY, MICH.

ANNE B. NORU-ANDER

	CALHOUN	Located In:	Corner Code ##		
	(County)				
1.	Public Land Survey	7 1 S R 5 W	A-13		
		T R			
		T R			
		T R			
2.	Property Controlling	S T R			
	in Section	S T R			
3.	Miscellaneous	S T R			
	Property in Sec.	S T R			

Register of Deeds Stamp & File Number

4.	Lot No,	, Recorded Plat	
3.	Private Claims		

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	В	C	D	Ë	F	G	Н	1 .1	K	L	N
2		 6		5—	L]_	\prod	3—] 1	
3	L	ــــ	\perp	\perp	1_	丄	$oldsymbol{ol}}}}}}}}}}}}}}}}}}$	\perp]		
4	L	ļ_	_	8	lacksquare	9	_	 10—	<u> </u>	1_	_ _1	2
5	L	1_	1	1	<u> </u>	\perp	1_	1_		_	_	
6	-	 18—	-	 17—	_	 16	$oldsymbol{ol}}}}}}}}}}}}}}}}}}$	 15—	<u> </u> _,!	4	¦	3 -
7	L	1_	<u> </u>	4_	<u> </u>	\perp	<u> </u>	1	Ш			
8	<u>_</u> .	 19—	\perp	 20	\perp	 21—	<u> </u>] 22—	2	3	2	4
9	<u> </u>	↓_	↓_	4-	<u> </u>	ļ	1	1	1_1	\Box	_	
10	L	 30—	 	29—	\perp	28	4	 27—	-2	6	2	5—
11	L	_	4	4_	_	1	4	_			_	
12	L	 31	\vdash] 32—	<u> </u>	 33—	┺	 34	3	5	3	6—-
13	┢_	_	L	1_	_	1_	1	ļ	L			<u>_</u>

A. Description of original monument and accessories and/or subsequent restoration:

TILE SET IN RESURVEY OF MARENGO TOWNSHIP IN 1825. RELOCATED IN SURVEY BY GIFFORD IN 1891. 10" MAPLE N 72° E 120 LINKS.

12" HICKORY N 74-3/4° W 190 LINKS.

LIBER 1707 PAGE 273

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND $1\frac{1}{2}$ " IRON PIPE IN TILE AS SET IN RESURVEY. RECORDED IN 1974 IN LIBER 1039, PAGE 442. 26" MAPLE N 55° E 61.59'.

14" HICKORY N 35° W 44.70'.

UTILITY POLE S 60° W 49.97'.

CORNER ACCEPTED AS TRUE CORNER AS PRESERVED BY LOCAL SURVEYORS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET HARRISON MONUMENT IN MONUMENT BOX IN GRAVEL ROAD.

PK NAIL 26" MAPLE N 55° E 61.35'.

NAIL & TAG 14" HICKORY N 35° W 44.53'.

P.K. NAIL 28" OAK N 50° W 65.42'.

WEST CORNER OF HOUSE FOUNDATION S 40° E 106.50'.

DONALD J.

DAVIS

PROFESSIONAL
SURVEYOR
NO.
17617

POFESSIONAL
APOFESSIONAL
APOFESS

Signed by

Surveyor's Michigan License No. (17617

Date SEPTEMBER 14, 1993.