

APPROVED

Date 9-15-99
CALHOUN COUNTY
REMONUMENTATION.
For corners in

CALHOUN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
CALHOUN COUNTY
RECORDED

29 SEP 1999 10:30:47 AM

ANNE B. NORLANDER
CLERK - REGISTER OF DEEDS

LIBER **2164** PAGE **714**

Register of Deeds Stamp & File Number

<u>CALHOUN</u> (County)	Located In:	Corner Code #
CONVIS TOWNSHIP		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>31</u> T <u>1S</u> R <u>6W</u>	<u>B-12</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, ROBERT R. CARR, in a field survey on AUGUST 11, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

THIS CORNER WAS NOT SET BY G.L.O.

ALTHOUGH NO RECORD OF SUBSEQUENT SURVEYS WERE FOUND, UNIFORM OCCUPATION ALONG 1/4 LINES INDICATES THAT THE SECTION HAS BEEN SUBDIVIDED.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND LONG STANDING 4" STEEL POST LEANING AT CENTER AND PLACED BERTSEN MONUMENT AT WHAT WOULD BE THE STRAIGHTENED LOCATION OF 4" POST

SURVEY &
REMONUMENTATION

MAR 13 2000

SECTION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BERTSEN MONUMENT IN STONES WITH CARSONITE WITNESS POST BESIDE.
6" WALNUT, N30°E 24.61 FEET SET NAIL AND SPOTTER
28" HICKORY, S50°W 9.72 FEET SET NAIL AND SPOTTER
15" CHERRY, S85°W 39.45 FEET SET NAIL AND SPOTTER
8" WOOD POST, N89°E 10.73 FEET SET NAIL AND SPOTTER

THIS POSITION NOT ESTABLISHED BY ORIGINAL GOVERNMENT SURVEYORS.
THIS MONUMENT IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE
POSITION OF THE CORNER.

Signed by [Signature]
Surveyor's Michigan License No. 20704 ROBERT R. CARR

