SECTION

10 10 10 No. 30

APPROVED

CALHOUN COUNTY REMONUMENTATION

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

REMONUMENTATION.	LAND CORNER RECORDATION CERTIFICATION Filing Requirement of Act 74, Mich. P.A. 19				
For corners in	1				

:35 PN

NDER OF DEEDS

p & File Number

CALHOUN	Located In:	Corner Code #	25 SEP 1998 2:27
(County)			ANNE B: NORLA CLERK - REGISTER
1. Public Land Survey	T <u>1S</u> R <u>6W</u> TR TR		LIBER 2062 PAGE 58
 Property Controlling in Section Miscellaneous Property in Sec. 	STR STR STR		Register of Deeds Stam
4. Lot No, Re	ecorded Plat		<u> </u>

in a field survey on <u>SEPTEMBER</u>, 19<u>98</u> I. ROBERT_R. CARR_ _ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1/4 POST COMMON TO SECTIONS 5 AND 8

A. Description of original monument and accessories and/or subsequent restoration:

SYVESTER SIBLEY D.S. 1826 SET ORIGINAL CORNER.

M.E. DEKEYSER R.L.S. #12019, 1971, SET 1/2" IRON AT PROPORTIONATE DISTANCE.

R.R. CARR P.S. #20704, AUGUST 1996, FOUND 1/2" IRON SET BY DEKEYSER ONE WITNESS REMAINING AND TOOK NEW WITNESSES.

1	1 1	3 (E 1				7 .	,	K I	. 1	4
1			Ī	<u></u>	· ·	Ī	·		Ī	·	T	1	Ì
2		<u> </u>		5 ~		<u> </u>	 ;	• •	:	Ż	 		ļ
3				>	 	ļ							ļ
4	<u> </u>	 		i Br ì		9 — ì	_1	1	1	1	1	2	1
5								ļ					
6	1	8	1	7-	1	6	1	5	1	4	1	3	į
7			}				ļ	<u> </u>					Ì
8	<u> </u>	9	2	0	2	1	2	2	2	3	2	4	ł
9		ļ											
10	3	o	—2	9	2	8	- 2	7	2	6	2	5	
11	\vdash						• • •						-
12	3	<u> </u> 1—	—э	2	3	3	3	4—	3	Ś	3	6	1
	1	ı		i	1	l			l		1		1

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON PER CARR 1996 WITNESSES AND REPLACED WITH BERNTSEN REMONUMENTATION MONUMENT STAMPED 20704.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BERNTSEN REMONUMENTATION MONUMENT WITH CARSONITE WITNESS POST ON NORTH SIDE. RAILROAD TIE POST IN EAST-WEST FENCE, NORTH 5.5 FEET 10" WHITE OAK, S89"W 27.90 FEET, SET SPOTTER 18" WHITE OAK, N23"W 17.85 FEET, SET SPOTTER 14" WHITE OAK, N31"E 6.97 FEET, SET SPOTTER

12" WHITE OAK, S62°E 27.06 FEET, SET SPOTTER

Surveyor's Michigan License No. ROBERT R. CARR

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORN

OF MICHIG ROBERT R. CARR PROFESSIONAL SURVEYOR No. 20704

gned by	Date <u>SEPTEMBER 16, 1998</u>

20704