## 

THURSDAY AND TON

## APPROVED

SECTION

Date 11-18-98 RRC CALHOUN COUNTY REMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

For corners in

Property in Sec.

CALHOUN Located In: Corner Code # PENNEIELD TOWNSIP 1. Public Land Survey T<u>1S</u> R 7W 2. Property Controlling in Section Т 3. Miscellaneous

19 NOV 1998 3:31:21 PM

ANNE B. NORLANDER CLERK - REGISTER OF DEEDS

LIBER 2079 PAGE 915

Register of Deeds Stamp & File Number

4. Lot No	, Record	led Plat		 	
5. Private Claims					
			1101/51/55	 	

in a field survey on NOVEMBER 6 \_, 19<u>\_\_98\_</u> I, ROBERT R. CARR that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed holow:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

NORTHEAST CORNER SECTION 3, NORTHWEST CORNER SECTION 2

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL CORNER SET BY SYLVESTER SIBLEY D.S. 1826

J.M. GIFFORD, RESURVEY, 1891, FOUND STUMPS OF BOTH BEARING TREES AND SET TILE.
D. DAVIS, CONSUMER POWER SURVEY, 1966, SET 5/8" IRON ON BASELINE IN LINE

WITH FENCE SOUTH.

R.R. CARR, P.S. #20704, 1992, FOUND 1/2" IRON IN MONUMENT BOX MATCHING DAVIS WITNESSES FROM 1966 AND ON BASELINE.

1	N 1	B	- P -	R F G	3 B	3 1	K L M
2	ļ	[ <b>6</b>	, \$	4	3	2	
3							;
4		) <b>7</b>	9	9	10	11	12
5							
6	1	B	- 17	16	15	14	13
7							
8	. 1	9	20	21	22	23	24
9		ļ'					.
10	3	0	29	28	27	26	25
11					-		
	3	1	32	33	34	35	36
		1	, , ,			-	

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON IN MONUMENT BOX MATCHING CARR WITNESSES FROM 1992.

REPLACED 1/2" IRON WITH BERNTSEN MONUMENT IN MONUMENT BOX.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

BERNTSEN MONUMENT IN MONUMENT BOX. 28" WALNUT, N78"E 61.99 FEET (NAIL AND SPOTTER)
10" MULBERRY, S65"E 71.48 FEET (NAIL AND SPOTTER)
20" HICKORY, S09"W 29.75 FEET (NAIL AND SPOTTER) 18" HICKORY, S67°W 64.19 FEET (NAIL AND SPOTTER).

AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

OF MICHIGAN CARR PROFESSIONAL BURVEYOR No. 20704 PROFESSION! Wessi Car

NOVEMBER 16, 1998

ļ

Surveyor's Michigan License No. 20704

Signed by

ROBERT R. CARR