MAR 3 0 1999

APPROVED

Date 9-16-98 PRC CALHOUN COUNTY REMONITATION

CALHOUN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF VICHIGAN CALHOUN COUNTY RECORDED

FOI COMEIS III			25 SEP 1998 2:28:32 PM
CALHOUN	Located In:	Corner Code #	ASSESS IN SUPERASSES
(County)			ANNE B. NORLANDER
PENNFIELD TOWNSHIP			CLERK - REGISTER OF DEEDS
 Public Land Surveγ 	T <u>1S</u> R <u>7W</u>	<u>M-8</u>	מתוח בחק
	T R		LIBER 2062 PAGE 587
	T R		
	T R	<u></u>	
2. Property Controlling	S T R		
in Section	S T R		
3. Miscellaneous	S R		
Property in Sec.	S		Register of Deeds Stamp & File Number
4. Lot No, Re	ecorded Plat		
			2 5 3 - 4 - 3 - 2 - 1

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

EAST 1/4 POST OF SECTION 24


A. Description of original monument and accessories and/or subsequent restoration:

I, ROBERT R. CARR , in a field survey on <u>AUGUST 19</u>, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a

Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed

SYLVESTER SIBLEY D.S. 1826, SET ORIGINAL CORNER
J.M. GIFFORD 1891 RESURVEY, FOUND STUMP OF ONE GOVERNMENT
BEARING TREE AND SET POST (TILE).
WITNESS CARD, NO NAME OR DATE.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

DUG EXTENSIVELY AT AND AROUND MIDPOINT OF EAST SECTION LINE.

LOCATION IS NORTH OF EAST AND WEST ROAD, BUT IN AREA MOST LIKELY DISTURBED WITH ROAD BUILDING.

FINDING NO EVIDENCE OF CORNER OR WITNESSES REMAINING, SET BERNTSEN REMONUMENTATION MONUMENT AT MIDPOINT OF EAST LINE OF SECTION 24 WITH CARSONITE WITNESS POST BESIDE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BERNTSEN REMONUMENTATION MONUMENT STAMPED 20704
CENTERLINE OF EAST AND WEST ROAD IS SOUTHERLY 32 FEET, MORE OR LESS, AT 90° TO CENTERLINE.
14" OAK, N05°W 10.20 FEET, SET SPOTTER
8" OAK, N43°W 54.45 FEET, SET SPOTTER
12" APPLE, N65°W 66.34 FEET, SET SPOTTER
NORTHEAST CORNER OF POLE BARN, S05°E 218.44 FEET.

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

ROBERT R. CARR
PROFESSIONAL SURVEYOR
NO. 20704

Signed by Signed by	Date SEPTEMBER 16, 1998
Surveyor's Michigan License No. ROBERT R. CARR 20704	