

**CALHOUN COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

**APPROVED**  
Date Nov. 20 1995  
**CALHOUN COUNTY  
REMONUMENTATION.**

For corners in  
Calhoun Located In: Corner Code #  
(County)

1. Public Land Survey	T <u>2S</u> R <u>5W</u>	<u>B-3</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

STATE OF MICHIGAN  
CALHOUN COUNTY  
RECORDED  
  
4 DEC 95 2:30 P.M.  
  
ANNE B. NORLANDER  
CLERK - REGISTER OF DEEDS  
  
**Register of Deeds Stamp & File Number**

I, Michael A. Groat, in a field survey on May 30, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3	7	8	9	10	11	12						
4												
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:  
 Lyon Gifford 1890  
 8" White Oak, N 30° W, 9 Lks 24" White Oak, S 77° E, 16 Lks  
 11" White Oak, S 77° E, 16 Lks


B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
 Found Iron set by R. Carr on a survey of parcels to the South. No other evidence remained. Old fence and tree row to the North and East. Accepted as a good perpetuation of the original monument.

CORNER  
REMONUMENTATION

FEB 22 1996  
COMMISSION

LIBER 1834 PAGE 265

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
 Set Berntsen monument with carsonite marker beside, from which:  
 Nail and spotter in U.P., S 50° E, 66.6'  
 Nail and spotter in Wood fence post, North 1.0'  
 Nail and spotter in 18" Oak, East, 23.40'  
 Nail and spotter in 12" Hickory, North, 14.55'



Signed by Michael A. Groat  
 Surveyor's Michigan License No. 39079

Date 11-18-95

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983

Surveyor's Michigan License No. 39079

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983