SECTION

## APPROVED

## Date 12-9-98 RCC CALHOUN COUNTY REMONUMENTATION.

## CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

15 DEC 1998 3:38:00 PM

	For corners in	corners in					ANNE D. NORLANDER								
	CALHOUN L	Located In:	Corner Code #			CLE		. B. RU REGIST			'n¢				
	(County)			ļ							טע.				
	MARSHALL	TOO DOWN	E 12		LIBER	200	11	PAGE :	/ن/						
	1. Public Land Survey	T <u>2S_R6W</u> TR	<u>F-13</u>												
		TR	· · · · · · · · · · · · · · · · · · ·	}											
	Ĭ	ΓR		ļ											
	2. Property Controlling S1	TR		1											
	in Section S T	rR		1											
	3. Miscellaneous S 7 Property in Sec. S 7	ΓR	<del></del>	ĺ											
-	Topolity in Oct.	''	<del></del>	<u> </u>	Regi	ter o	Dee	de Star	np &	File	Num	<u>ber</u>			
	4. Lot No, Recorded Plat _		, <del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>		а в	C D	E	F G	нј	J	к	ъ 1			
	5. Private Claims	<u></u>		1		ŢŤ	7	TT	ĪĪ		7	Ī			
				2	6-	5	-	4-	-3	2 -		1-			
				3		1	_	<del>                                     </del>	11			1			
	I, Michael A Groat , in a field su requirements of P.A. 74, Michigan P.A. of 1970	urvey on <u>December 7</u>	_, 19 <u>98</u> _ do hereby state that u	ınder 4		+- 8		9	-10	1 1 )	+	12			
	conformance with regulations and rules therefore	as required in the curren	t manual of survey instructions o	of the 5	<del> </del>	+		<del>                                     </del>	+-	-		<del> </del>			
	United States Department of the Interior, Bureau that the corner points mentioned in lines 3, 4 and				16-	<del>-}-</del> i	<del>}                                    </del>	16	15—	14-		1 3			
	Board of Land Surveyors or by a Decree of							╂╾┼╴	+			+			
	recovered, found as expressed below:			8	19-	2	<b></b>	21	22-	23-	+-;	24			
	NOTE: Not more than 2 corners, all in the	e same town and rand	e. may be recorded	9	<del></del>	++		<del>                                     </del>				<del> </del>			
	on this certificate.		,-,,	10	-30-	29		2 <del>0  </del>	27—	26-		25_			
				11		+	<del></del> -					-			
				12	-31-	32		3	34	35_	;	3 <del>6</del>			
				13			],	<b>_</b>			_l	<u> </u>			
A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL SURVEY BY LUCIUS LYON, DEPUTY SURVEYOR, 1825, SET POST, TAM, 7", N 76 1/2° E, 32 LKS, TAM, 6" N 56° W, 29 LKS.															
	AMES GIFFORD, 1891, FOUND STUMPS OF OLD BEARING TREES, SET STAKE, 6" TAM, I 59° W, 30 LKS, TAM, 8", N 16 3/4 ° W, 66 LKS														
	Description of corner evidence found														
			•	•											
	FOUND HOLLOW TILE WITH STEEL PIN INSIDE AT FENCE INTERSECTION, ACCEPTED THIS AS A FAITHFUL AND CAREFUL PERPETUATION OF THE ORIGINAL MONUMENT.														
	C. Description of monument for corner an			g the positi	ion of	the co	rner:								
	SET BERNTSEN MONUMENT WITH CAR NAIL & TAG IN 6" ASH, WEST, 20.67"	RONITE MARKER C	ON NORTH SIDE.	<u>.</u>		OF A	ALC:	<b>.</b>							
	NAIL & TAG IN 8" ASH, S 80° E, 23.80' NAIL & TAG IN 8" ASH, SOUTH 21.05'			<b>A</b>	187 E	*******		2							
	NAIL & TAG IN 10" CHERRY, N 5° E, 11.1	10'		<i>₹</i> ∗	M	CHAI	EL A.	13.1	i.						
	•			# * f	•	SHO	AT.	1.	Ł						
'				10	PRO	FESS! JRVEY	ONAL	. J	<b>*</b>						
					<b>(</b> )	No.	UR	12	7						
	•			- T	A. AREAN	To the	-	U ARE	•						
	Signed by Mill a. f			7	AO	E S S I	ONAL								
;	Signed by MA A. E.			Date <u>Dece</u>	. 44.55										
:	Surveyor's Michigan License No. 39079														