SLIAVEY & **REMONUMENTATION**

MAR 2 1 1997

COMMISSION

A P	PA	OV	750	$D_{\lambda,0}$
Date <u>/</u>	20	16	197	LHAM
CALI	1 6 7 6 7 6 V		JMI	· W

CALHOUN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN CALHOUR COUNTY RECORDED

40 DET DZ 947A D 14

ьо	r corners in					10 UC 70 2:00 F.M.			
Calhoun [County]		Located In:		ed In:	Corner Code =##	ANNE B. HORLAHDER			
1.	Marshall Township Public Land Survey		т 2	S _R 6W	J-13	CLERK - NEGISTER OF DEEDS			
			T	R		4 ለ ለ ተ ማ ማ ለ መ			
			T	R	/	LIBER 1893 PAGE 305			
			T	R					
2.	Property Controlling	S	T	R					
	in Section	S	, , T	R					
3.	Miscellaneous	S	T _	R		Register of Deeds Stamp & File Number			
	Property in Sec.	S	T	R					
4.	Lot No, Re	ecorde	ed Plat _			ABCDEFGHIJKL			
5	Private Claims								

October 14 19 96 William K. Crane, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Survey Lucius Lyon, 1825:	By James Gifford, 1890:			
12" W. OakN25°E85 links 12" D.ON50°W41 links	Placed corner in line with fence North and 6 links West of the line fence South.			
	12" W.OakS60°E59 links 6" Yellow OakN54°W78 links			

6 7 8		8-	—17- ——20	1	6	-15 	1 2	3-	13-
9		Ц	$\vec{\perp}$			-	╁	$oxed{oxed}$	
10	3	0			28	27-		6—	25
11	 	\vdash	\vdash	 		+		<u> </u>	
12	<u> </u> 3	1	—32		33-	-3 4	╬	5	36-
13	<u> </u>		Ц.		$\perp \perp$		<u>ا</u>	-	
LCRC, by Rol	L. er	110 t Ca	06, arr:	P. 9	14, 1	.976			<u></u>

bituminous road in line with fence North.

1½ " iron pipe......East.......3.96' Chain link fence corner.....North.....32.88 Chain link fence corner......S5°E.....35.95

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron stake in centerline of bituminous surface as recorded in 1976 LCRC above.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 1/2" iron stake with standard Calhoun County Remonumentation Monument (Bernsten Monument) and a monument box.

29243

WILLIAM K. SURVEYOR Set nail & tag in 16" Maple.....N75°E......72.54' Face of corner steel fence post for 6'high chain link NO.
29243 29243 CAND SURMINIME 1/2" iron for Fredonia Cor.....East...........3.86' This is accepted as the best available evidence of the position of the original corner. Signed by William K. Crane
Surveyor's Michigan License No. Date <u>October 16, 1996</u>