CALHOUN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970

AP	PF	IOI	E	
Date	md.	18	190	75
		N CO		
WAS EVER 2.	9. 3. 1 5 5 K	7 50 8 2	1 10 - 100	h 4

For corners in		raing nequire	ement of Act 74, Mich. P.	REMOTION COURTY
	Calhoun	Located In:	Corner Code ##	Le Confistation Control of the Contr
	Emmett Township			
1.	Public Land Survey	T <u>2S </u>	B-9	STATE OF NICHIGAN CALHOUR COUNTY RECORDED
2.	Property Controlling In Section	S T R S T R		26 OCT 95 10:14 A.H.
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number CLERK - REGISTER OF DEEDS
4.	Lot No , R	ecorded Plat		——— ARCDEFGHIJKL

I, Donald J. Davis , in a field survey on November 10 , 1994 ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Original survey in 1826 by Sibley.

Resurvey in 1889 by Hodgeman.

Tile set.

5. Private Claims

6" Burr Oak S 36° E 81-3/4 links.

5" White Oak N $63\frac{1}{2}$ ° W 5 links.

Corner used by MDSH on survey of Hwy I-94.

Corner used for platting of Rolling Hills,

L 17, Р. 22.

LCRC recorded on July 12, 1995, in Liber 1810, page 9.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found RR spike. Dug and found clay tile.

Accepted as perpetuation of corner location.

CONTROL !

LIBER 1828 PAGE 64

FEB 2 2 1996

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Bernsten monument with monument box.

Nail & Tag Utility pole N 30° E 54.60'.

Nail & Tag MDSH R/W marker N 85° W 33.00'.

Nail & Tag 40" Oak N 80° W 33.35'.

Nail & Tag Utility pole S 20° W 106.00'.

Nail & Tag Guy Pole S 50° E 73.60'.

Signed by Doriald J. Davis
Surveyor's Michigan License No. 27617

Date October 9, 1995

DONALD J. A DAVIS

PROFESSIONAL SURVEYOR

NO. 17617

17617

17617

FORM APPROVED BY MICHIGAN STATE 80ARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983