APPROVED

Date 9-15-99 RECALHOUN COUNTY
REMONIMENTATION

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	ION.		1
CALHOUN	Located In:	Corner Code #	STATE OF MICHIBAN CALHOUN COUNTY
(County)	-	· ;	RECORDED
EMMETT TOWNSHIP 1. Public Land Survey	T_2S_R_7W	E-3	
1. Fublic Land Survey	TR		29 SEP 1999 10:30:15 AM
·	TR		
	TR		ANNE B. NORLANDER
2. Property Controlling	S TR	 ,	CLERK - REGISTER OF DEEDS
in Section	S		LIBER 2164 PAGE 712
3. Miscellaneous	S T R		, i
Property in Sec.	S T R		Register of Deeds Stamp & File Number
4 int No Rec	orded Plat		
	Joided Flat		<u>. </u>
			A B C D E F G B 1 J K L
	:		2 6 5 4 3 2 1
that under requirements of P.A. and 2 above were in conformal manual of survey instructions of Management or by a decree of a and 5 above were in conforman Decree of a Court of Law; established below:	A field survey onAUGUST 4 74, Michigan P.A. of 1970, the conce with regulations and rules the of the United States Department a Court of Law and for that the conce with the rules of the Michigan plished, re-established, monumented as, all in the same town and range,	corner points mentioned in lines erefore as required in the curre of the Interior, Bureau of La rner points mentioned in lines 3, Board of Land Surveyors or by ed, recovered, found as express	1
on this certificate.	بنه المنافقة المنافق منافقة المنافقة المن	, may be recorded	10 30 29 28 27 26 25
A. Description of original mo	onument and accessories and/o	or subsequent restoration:	11 32 33 34 35 36
ORIGINAL CORNER SET BY SYLV	VESTER SIBLEY 1826.		13
AT POINT WHERE MR. MILLER S	89, FOUND STAKE AT ANGLE OF AYS HE HAS KNOWN THE CORNI AND MARKED HICKORY 12" N1W	ER FOR A	
	E 45 BY HERBERT J. ADAMS 191 COMMON TO SECTIONS 4, 5, 8		
WITNESS BY CARR TO 1-1/4" IR	ON PIPE 1968 AND UPDATED 19	78.	!
	•		•
B. Description of corner evi	dence found and/or method ap	oplied in restoring or reestabl	shing corner:
PLAT OF FAIRFAX. THIS IRON N	E OR LESS BELOW SURFACE FOR MATCHES WITNESS BY CARR FRO 93.5 FEET TO CENTER WHICH A	OM 1968 AND 1978 TO 1-1/2"	PIPE.

BE RESURVEY WITNESS BY HODGMAN (Y OAK 8 N88E 141 LKS).

REPLACED 5/8" IRON WITH BERNTSEN MONUMENT IN MONUMENT BOX.

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BERNTSEN MONUMENT IN MONUMENT BOX NW CORNER OF HOUSE NO. 134, S52°W, 41.65 FEET NE CORNER OF HOUSE NO. 134, S05°W 42.53 FEET 36" OAK, N86°E 71.08 FEET, SET NAIL AND SPOTTER 12" MAPLE, NO1°W 46.30 FEET, SET NAIL AND SPOTTER

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

Signed by _ Surveyor's Michigan License No. 20704

ROBERT R. CARR

OF MICHIG ROBERT R. CARH PROFESSIONAL 20704 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983