A			P.	0	W		Bon.
)ai	e /	<u> </u>	-)	2	l	76	,080
C/	ari Ma	}	154	((). [] []	CU	117	Y M

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

G-2

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

Calhoun Located In: Corner Code ##

19 NOV 96 1:53 P.M.

Emmett Twp

For corners in

1. Public Land Survey Sec 4

T 2 S R 7 W T ____ R ____ T ____ R _ T ____ R ____

ANNE B. NORLANDER CLERK - REGISTER OF DEEDS

2. Property Controlling in Section

T ____ R ___ __ T ____ R ____

LIBER 1899 PAGE 601

Miscellaneous Property in Sec.


__ T .___ R __ S __ R ___

Register of Deeds Stamp & File Number

_ , Recorded Plat _

5. Private Claims

i, Robert R. Carr, in a field survey on October 23, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:



Emmett Township

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826. G.L.O.; S. Sibley,

Resurvey; Hodgeman, 1889, found stake at intersection of bearings N60-1/2W 8-1/2 links from Yellow Oak 16" bearing tree of resurvey of R.H. Merritt set post (tile) no other trees near.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 2'x3" solid tile over another 3" solid tile, 3'x5/8" rebar with cap no. 29245 beside tile, also old spline gear laying beside tile. SURVEY & Accepted tile as true perpetuation of corner. REMONUMENTATION

MAR 2 1 1997

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced top tile with Berntsen Calhoun County Remonumentation Monument with

Carsonite witness post 1 foot south.

Nail & spotter Southerly side U-Pole N85°E 49.12 feet.

Nail & spotter Westerly side twin 18"-20" Oak S26°E 64.55 feet.

Nail & spotter Easterly side 28" Oak N28°E 119.63 feet.

Nail & spotter Westerly side 6" Oak S40°W 14.40 feet.

The second of May CORM MYPESSION Mo. 20704 A TENENT

Signed by _

Robert R. Ca Surveyor's Michigan License No.

20704

Date November 8, 1996