

**SURVEY &
REMONUMENTATION**

APPROVED

ate 10-19-94 *(Signature)*
**CALHOUN COUNTY
REMONUMENTATION.**

APR 26 1995
CALHOUN COUNTY REMONUMENTATION

LAND CORNER COMMISSION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Calhoun

(County)

Located In:

Corner Code #

- | | | | | | |
|---------------------------------------|---|------------|---|------------|------------|
| 1. Public Land Survey | T | <u>2</u> S | R | <u>7</u> W | <u>G-8</u> |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| 2. Property Controlling in Section | S | _____ | T | _____ | R |
| | S | _____ | T | _____ | R |
| 3. Miscellaneous Property in Sec. | S | _____ | T | _____ | R |
| | S | _____ | T | _____ | R |
| 4. Lot No. _____, Recorded Plat _____ | | | | | |
| 5. Private Claims _____ | | | | | |

STATE OF MICHIGAN
CALHOUN COUNTY
RECORDED

25 OCT 94 9:01 A.M.

ANNE B. NORLANDER
Register of Deeds Stamp & File Number

I, Donald J. Davis, in a field survey on October 21, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

Original survey in 1824. Resurvey in 1889 by Hodgman, tile set.
Corners used by MDSH on survey of I-94.
12" Sassafrass N 20° E 51.28'
1957 SE corner bldg, NW 107.75'
Power pole S 45° W 86.05'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron from MDSH information.
Accepted as perpetuated corner.

LIBER 1773 PAGE 881

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Iron rod.
Power pole S 30° E 92.72'
14" Elm S 35° W 87.70'
16" Maple N 45° W 69.05'
NW corner R.R. rail post N 60° E 29.85'
Power Pole S 45° W 86.05'



Signed by Donald J. Davis
Surveyor's Michigan License No. 17617

Date February 23, 1994