APPROVED

Date 10-20-99 PKC CALHOUR COUNTY REMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Property in Sec.

Corner Code # Located In: CALHOUN (County) **EMMETT** T2S R7W 1. Public Land Survey R 2. Property Controlling R in Section 3. Miscellaneous R

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

3 DEC 1999 2:43:06 PM

ANNE B. NORLANDER CLERK - REGISTER OF DEEDS

LIBER 2182 PAGE 425

Register of Deeds Stamp & File Number

l. Lot No,	Recorded Plat
5. Private Claims	

, 19 99 do hereby state that under , in a field survey on <u>October 5</u> requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

АВ	C	D E	F G	н 1	t J i	LI
1						
2 - 6		5 — †	- 4	<u>\$</u>	ż	1
3		} }-				
4		ę	ــو ـ	10	11	12
5		 				-
6 -18	,	7	-16	15	14	13
7		 				
8 -19	·	0	-21	22	23	24
9		 				
10-30			-28	-27	-26	25
11	_ -	}				
12-31		2	-33	34	35	-36-
194	L	<u> </u>				L

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL SURVEY, SYLVESTER SIBLEY, 1826, SET POST 40.00 CHAINS, B. OAK, 15" SOUTH 24° WEST, 21 LINKS; B. OAK, 18", NORTH 88° EAST, 37 LINKS RE-SURVEY, F. HODGEMAN, 1887, FOUND OLD STAKE AND STUMP OF BEARING TREE SET POST, MAPLE 14", NORTH 76° EAST, 20 LINKS, W. OAK, 8" SOUTH 39" EAST 48 LINKS 1957, MSHD, 1" IRON STAKE OVER TILE, 10" COTTONWOOD, NORTH 45° WEST, 18.10"; APPLE, NORTH 55.5"; 45" OAK, SOUTH 50° WEST, 51.10"; 12" TWIN CHERRY, NORTH 50° EAST, 27.44"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" X 4" PIPE NEXT TO LARGE ROCK, EXCAVATED & FOUND THIS CORNER FALLS ON A STEEP SLOPE CREATED WHEN I-94 WAS CONSTRUCTED. ACCEPTED THE PIPE AS THE BEST EVIDENCE OF THE ORIGINAL CORNER.

C. Description of monument for comer and accessories established to perpetuate locating the position of the

SET BERNTSEN MONUMENT IN PLACE OF PIPE NAIL & TAG IN 6" LOCUST, SOUTH 40° EAST, 35.40' NAIL & TAG IN 10" SHAGBARK HICKORY, NORTH 75° EAST, 87.55' NAIL & TAG IN 3" HICKORY, NORTH 10° EAST, 8.75' NAIL & TAG IN 8" APPLE, NORTH, 55.3' CARSONITE MARKER, SOUTH 45° WEST, 1.67'

Signed by Tell (1. Surveyor's Michigan License No. 39079

OF MICHIGAN MICHAEL GROAT PROFESSIONAL No. 39079 10/12/99 Date

A APPROVED BY MICHIGAN STATE BOARD OF PROPI

MAR 1 3 2000

SURVEY &

REMONUMENTATION

SECTION

MAY 44,4976

D. MAIL . 1865