FFB 2 2 1996

COMMISSION

CALHOUN COUNTY REMONUMENTATION LAND CÖRNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

							•
A	P	P	R	0	V	R	T

Date Nov. 25 1905 CALHOUN COUNTY REMONHMENTATION.

CALHOUN COUNTY RECORDED

4 NEC 95 2:26 P.M.

ANNE R. NORLANDER CLERK - REGISTER OF DEEDS

Register of Deeds Stamp & File Number

10

	COMICIO III		
	CALHOUN (County)	Located In:	Comer Code ≠#
В	ATTLE CREEK C	ITY	
1.	Public Land Survey	T <u>2S</u> R 8 W	E-3
		T R	
		T R	
		T R	· · · · · · · · · · · · · · · · · · ·
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

_ . Recorded Plat __ 4 Lot No. 5. Private Claims _____

I, ROBERT R. CARR, in a field survey on OCTOBER 24 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, SIBLEY, 1826. HODGEMAN, 1887, FOUND OLD STAKE HOLE AT INTERSECTION OF ROADS,

BEARING TREES GONE, SET TILE.

M.S.H.D. 1961 FOUND 1-1/2" PIPE WITH BRICK AROUND.

M.S.H.D. 1977 FOUND PIPE .

L.C.R.C. BY CRANE, 09/09/91, FOUND 1-1/2" PIPE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1-1/2" PIPE DISTURBED BY RECENT CONSTRUCTION, WITH PIECES OF BRICK AT BOTTOM.

RE-ESTABLISHED LOCATION FROM CRANE & M.S.H.D WITNESSES.

HERFE 1834 PAGE 257

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET BERNTSEN CALHOUN COUNTY REMON MONUMENT WITH CARSONITE OF BICA

WITNESS POST ON SOUTH SIDE AND STONES AROUND MONUMENT.

CONCRETE MONUMENT, S32°E, 28.50 FEET.

ANGLE IRON CORNER POST, S87°E, 106.42 FEET.

CONCRETE MONUMENT, S56°W, 162.24 FEET.

TWIN 10"-14" MAPLE, S11°E, 120.58 FEET. (NAIL & SPOTTER)

TOP NUT OF F-HYDRANT, S86°E, 171.28 FT.

Signed by Robert

Surveyor's Michigan License No. 20704

__ Date ___NOVEMBER_17, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

Aobert R

A OFFICE

CARR

REVISED JAN., 1983