

APPROVED

DATE Dec 18 1995
CALHOUN COUNTY
REMONUMENTATION.

Calhoun County Remonumentation
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
CALHOUN COUNTY
RECORDED

12 JAN 96 10:25 A.M.

ANNE B. NORLANDER
CLERK - REGISTER OF DEEDS

LIBER 1839 PAGE 651

Register of Deeds Stamp & File Number

Calhoun (County)	Located In:	Corner Code #
City of Battle Creek (B.C.Twp)		
1. Public Land Survey	T <u>2 S</u> R <u>8 W</u>	<u>F-9</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Donald J. Davis, in a field survey on May 10, 1995,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- Original survey in 1826 by Sibley. Iron set by Carr in 1992 from 1957 witnesses.
 - Resurvey in 1886 by Hodgeman. Tile was gone.
 - Tile Set. 10" Elm S 56° W 22.02'
 - 12" Red Oak S 57° W 54 links. 30" Elm N 6° W 15.86'
 - 8" Elm N 87° E 80 links. 10" Elm N 77° W 32.36'
 - Tile found 1957. LCRC recorded July 12, 1995 in Liber 1810, page 8, for plat by Davis, Jacaranda Woods No.2.
 - 36" Elm S 50° W 43.24'
 - Utility pole East 68.02', Utility pole West 46.56'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found iron set by Carr in 1992.
 - Accepted as perpetuation of original corner location.

REMONUMENTATION

FEB 22 1996

COMMISSION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Set Berntsen monument.
 - Nail & Tag Fence Post East 3.00'
 - Nail & Tag 30" Elm N 6° W 15.86'
 - Nail & Tag 12" Elm N 75° W 32.36'
 - Nail & Tag 10" Elm S 55° W 22.05'



Signed by Donald J. Davis
Surveyor's Michigan License No. 17617

Date January 8, 1996