

**SURVEY &  
REMONUMENTATION**

APR 26 1995

**APPROVED**

**COMMISSION  
CALHOUN COUNTY REMONUMENTATION**

Date 10-19-94  
**CALHOUN COUNTY  
REMONUMENTATION.**

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
Calhoun  
(County)

Located In: Corner Code ##

1. Public Land Survey	T	<u>2</u> S	R	<u>8</u> W	<u>K-6</u>	
	T	_____	R	_____	_____	
	T	_____	R	_____	_____	
	T	_____	R	_____	_____	
2. Property Controlling in Section	S	_____	T	_____	R	_____
	S	_____	T	_____	R	_____
3. Miscellaneous Property in Sec.	S	_____	T	_____	R	_____
	S	_____	T	_____	R	_____

STATE OF MICHIGAN  
CALHOUN COUNTY  
RECORDED

25 OCT 94 9:02 A.M.

ANNE B. NORLANDER  
CLERK - REGISTER OF DEEDS

**Register of Deeds Stamp & File Number**

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Donald J. Davis, in a field survey on March 28, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules theretore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

Tile set in resurvey, in 1887 by Hodgman.  
Tile destroyed by street construction.  
Iron stake set and used in local surveys.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" solid iron in monument box in Capital Avenue.  
This corner is as used for adjacent plats and surveys.

LIBER **1773** PAGE **883**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" solid iron in monument box.  
Nail & Tag Utility pole S 85° E 30.70'  
Nail & Tag utility pole N 40° W 63.34'  
Nail & Tag Utility pole S 30° E 109.02'  
SE corner foundation bldg N 60° W 86.44'



Signed by Donald J. Davis Date March 29, 1994  
Surveyor's Michigan License No. 17617