APPROVED

For corners in

5. Private Claims

recovered, found as expressed below:

| Date | 9-1 | 5 | -99 | je | RL |
|------|-----|----|------|------|----|
| | | | COUI | | |
| REM | ONU | ME | NTAT | ION. | • |

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE 'OF MICHIGAN CALIBURA COURTY RECORDED.

| CALHOUN | | Located in: | Corner Code # | | |
|-------------------------|---|-------------|--|--|--|
| (County) | | ! | | | |
| ALBION TWP | | | | | |
| Public Land Survey | | T.3S R.4W | <u>M-10</u> | | |
| • | | TR | | | |
| | | TR | ļ | | |
| | | TR | | | |
| 2. Property Controlling | 8 | TR | | | |
| in Section | S | TR | | | |
| 3. Miscellaneous | S | TR | | | |
| | 6 | 7 0 | | | |
| Property in Sec. | o | | ************************************** | | |

, Recorded Plat

29 SEP 1999 10:31:23 AM

ANNE B. NORLANDER CLERK - REGISTER OF DEEDS

LIBER 2164 PAGE 715

Register of Deeds Stamp & File Number

| | • | | • |
|--|--------------------------------|-------------------------|-------------------------------|
| I, Michael A. Groat requirements of P.A. 74, Mich | | | |
| conformance with regulations | | | |
| United States Department of the | | | |
| that the corner points mention | sunde it lone & C sent of free | v annerrentenn ei aneuv | ith the rules of the Michigan |

Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A. J | B (| C 1 | , 1 | B . 1 | F (| 3 1 | ä | 1 . | J 1 | K 1 | . 1 |
|----|------------|--------------|-----|--------|--------------|------------|----------------|----------------|-----|----------------|----------|-------------|
| 1 | Γ_ | | | | | | | | | Γ | | |
| 2 | } ; | 6 | | • | | • | : | ġ | | <u> </u> | - | i |
| 3 | ļ | | ļ | | <u> </u> | ├ | ├ | ├ | | _ | ļ | |
| 4 | <u> </u> | | | | - | 9 ! | 1 | | _1 | 1 | 1 | 2 |
| 5 | - | ⊢ | | | | | | | - | }— | | |
| 6 | <u>_</u> 1 | 9 I | 1 | , , | _1 | 6 ! | 1 | 5 | 1 | 4 | 1 |] 3 |
| 7 | | | | | | ļ | | - | | - | ├ | |
| 8 | 1 | 9 | -2 | 0 | 2 | 1 | 2 | 2 | 2 | 3 I | 2 | |
| 9 | | | | | ļi | | | - | | | | |
| 10 | 3 | 0 | | 9 | | . | | (!7 | 2 | | 2 | 5 |
| |) | | | Ĺ | | ا_ا | | ĺ | | Ĺ | | G |
| 11 | | | | | | | | | | | | |
| 12 | 3 | 1 | 3 | 2 | 3 | 3 | 3 | 4 | -3 | S | 3 | 6 |
| | | 1 | | 1 ! | | | 1 3 | 3 | | ł | 1 1 | |

A. Description of original monument and accessories and/or subsequent restoration:


ORIGINAL SURVEY, 1825, LUCIUS LYON, DEPUTY SURVEYOR, SET POST. BURR OAK, 5" S 69 W, 64 LINKS, BURR OAK, 8", S 51° W, 64 LINKS.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND IRON IN CENTERLINE OF ROAD, IN LINE WITH FENCE WEST. EXCAVATED AND FOUND ANOTHER 1/2" IRON BENEATH FOUND NOTHING ELSE. ACCEPTED THIS POSITION AS THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER SET BY LYON.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET A BERNTSEN MONUMENT IN MONUMENT BOX. NAIL & TAG IN 12" BURR OAK, SOUTH 56° WEST, 40.17 FEET NAIL & TAG IN 15" CHERRY, NORTH 30° WEST, 51.17 FEET NAIL & TAG IN 15" SHINGLE OAK, NORTH 26" EAST, 59.36 FEET NAIL & TAG IN 15" WHITE OAK, SOUTH 09" EAST, 99.38 FEET.



MAN U.N.

Surveyor's Michigan License No. 39079

D MAY 14,1978

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION