CALHOUN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| Date No. 20 1905 |
|-----------------------------|
| REMORYMENTATION. |
| CALHOUN COUNTY; RECORDED |

| | | • . |
|-------|---------|-----|
| ⊢nr r | corners | ın |

Property in Sec.

Calhoun Located In: Corner Code ≠ Eckford Township T 3 S R 5 W 1. Public Land Survey T _____ R ___ ____ R _ __ R _ __ T ____ R __ 2. Property Controlling in Section ___ T ____ R ___ 3. Miscellaneous

4 DEC 95 2:22 P.M.


ANNE B. NORLANDER CLERK - REGISTER OF DEEDS

Register of Deeds Stamp & File Number

..... , Recorded Plat _ 5. Private Claims ___

i, William K. Crane, in a field survey on February 7 $do \,hereby\,certify\,that\,under\,requirements\,of\,P.A.\,74, Michigan\,P.A.\,of\,1970, the\,corner\,points\,mentioned$ in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Original Survey 1825, Lucius Lyon:

9" Hickory S 77° E N 84-3/4° W 162 links 24" W. Oak

73 links

B.F. Welles, April 12, 1880:

Found bottom of both witnesses and put in a marble 3 x 3, 18" long.

Stone wall, 52 links North to nearest side.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rerod fitting occupaton. No other previous witnesses were left. Accepted as corner location.

المساجاة لأتهاني REMONUMENTATION

LIRER 1834 PAGE 248

| FEB 2 2 199 | 6 | | | |
|--|---------------------|---------------------------|---------------------------------------|---------------------|
| COMMISSI | ION | | | |
| C. Description of monument | for corner and acce | essories established to I | perpetuate locating the position | of the corner: |
| Replaced 1/2" rerod in a monument box. | with standard | Calhoun County I | Remonumentation Corner | (Bernsten Monument) |
| 20" Hickory | s 10° W | 28.201 | | S |
| 6" Maple | и 30° и | 45.53 | # # # # # # # # # # # # # # # # # # # | , WILLIAM K. |
| 6" Maple | N 15° E | 33.22' | * | CRANE 4 |
| 5" Birch | S 80° E | 61.58 | 異常 | SURVEYOR # |
| Centerline of | | | | NO. |
| Bit. Road | North | 2 1 ± | | 29 243 |
| Fence to North | East | 2¹ ± | • | LAND SURVINIE |

This is accepted as the best available evidence of the

Signed by William K. Crane

29243 Surveyor's Michigan License No. _

NO. 29243 P. C. 29243 LAND SURVENIENT TO SUR _____ Date <u>November 20, 1995</u>

NO. 29243 LAND SURVENIEN