APPROVED

Date 12-9-98 RAC CALHOUN COUNTY REMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF HICHIGAN CALHOUN COUNTY RECORDED

15 DEC 1909 3:33:14 PM

REMONUMENTATION.	 Filing Req 	uirement of Act 74, Mich. P.A. 1	22 12 DEC 1998 2:22:14 LU
For comers in		į	ANNE B. NORLANDER
	cated In:	Corner Code #	CLERK - REGISTER OF DEEDS
Calhoun (County)			መለጠመ ጠጣለ
Leroy Township 1. Public Land Survey	T3S R8W TR TR TR	G-10	LIBER 2087 PAGE 920
2. Property Controlling S in Section S	TR TR		
3. Miscellaneous S Property in Sec. S	TR		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ŧ		ABCDEFGHIJKLM
4. Lot No, Recorded Fize 5. Private Claims	·		1 2 1 1 1
5. Private Claims			2 - 6 - 5 - 1 - 1 - 1 - 1 - 1
			3
I. William K. Crane , in a field surve requirements of P.A. 74, Michigan P.A. of 1 conformance with regulations and rules the the United States Department of the Interior and for that the comer points mentioned in Michigan Board of Land Surveyors or the monumented, recovered, found as express	refore as required in or, Bureau of Land Ma- lines 3, 4 and 5 above by a Decree of a Co and below:	the current manual of survey instructions that an agament or by a decree of a Court of Lavive were in conformance with the rules of the Court of Law; established, re-established	6 18 17 16 15 14 13 18 18 18 18 18 18 18 18 18 18 18 18 18
NOTE: Not more than 2 corners, all in	the same town and	d range, may be recorded	10 30 29 28 27 26 25
on this certificate.			
Oli ulib volument			31 32 33 34 35 36
			12 -31 -32 -33
A. Description of original monument	and accessories	and/or subsequent restoration:	13
GLO Robert Clark, 1826:	/ 36 links		·
13" W. Oak N 77° W 8" W. Oak N 64°E	11 links		and a mark of A
Resurvey, Hodgman, 1885: Found stake and U.S. bearing	g trees both standi	ing. Set post with brick under.	SURVEY & REMONUMENTATION
· Option Comme			መለከ © ለ 4ስስስ
•			MAR 3 0 1999
Chambers, no date: 173.6' South of face 4" iron fe	nce post		
1/3.6 South of face 4 hours	4.7'		SECTION
12" Fim East	3,5		SECTION
14" Hickory S 80° W	46.7'		
•••••			
			in a samon
a section of comer evidence	found and/or met	hod applied in restoring or reestablish	ing corner.
B. Description of contact endones		Fundamental 6' v 8' area 4' deep and	I could not find tile. Established corner at intersection
Found traces of ancient fence come of fences North, South and East at	er post in stone pit position of old cor	ner post in stone pile.	d could not find tile. Established corner at intersection
		·	the position of the comer:
C. Description of monument for co	orner and accessor	ries established to perpetuate locating	the best available evidence of the location
a A Landard Calhaum County Rom	nonumentation mo	nument (Berntsen monument) and is	accepted as the same
of the original corner.		24 621	. autilities
Nail and tag in 6" Cherry	N 45° W	21.82' 23.60'	MANUAL OF ASIA
Neil and tag in 12" Cherry	S 80° W	5.10'	MINTATE
Mail and tag in 12" ASh	S 15° W	18.77'	A STATE OF THE STA
Nail and tag in 4" Cherry	S 55° E		WILLIAM K.
	•		CRANE 4
			SURVEYOR
			16 NO. 14 E
11. I	· D	mail Danamhor 0 10	198 29243
Signed by <u>Willia K</u>	Cran	Date December 9, 19	W. Sch ave ill
Signed by	K. Crane, P.S.		TAME LAND SUMMIT
William	K. Crane, P.S.		WILLIAM K. WILLIA
) LL 1/4 4		

Surveyor's Michigan License No. 29243