

APPROVED

Date 8-17-94  
CALHOUN COUNTY  
REMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Calhoun (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>3</u> S R <u>8</u> W	M-5
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

STATE OF MICHIGAN  
CALHOUN COUNTY  
RECORDED

18 AUG 94 12:08 P.M.

ANNE B. NORLANDER  
CLERK - REGISTER OF DEEDS

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

Donald J. Davis, in a field survey on August 10, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- Tile set in resurvey of 1884 by Hodgeman.
- 1/2" iron set by Dekeyser & Assoc. over tile.
- 18" Hickory N 43° E 29.05'
- 14" Maple N 78° E 83.00'
- 12" Maple S 74° E 24.10'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- Found iron rod and tile under with rocks around.
- Accepted as true location of corner.

LIBER 1763 PAGE 760

SURVEY &  
REMONUMENTATION

OCT 24 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Set Berntsen monument and monument box, 2 feet West of East edge paving.
- Nail & Tag 36" Oak N 30° E 56.88'
- Nail & Tag 14" Maple N 60° E 31.45'
- Nail & Tag Utility Pole S 80° E 101.25'
- Nail & Tag 4" fence post S 40° W 36.43'



Signed by Donald J. Davis

Date August 17, 1994

Surveyor's Michigan License No. 17617