CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

Date Like SP, 1945
CALHOUN COUNTY
REMONUMENTATION

For cor	mers in	Linna ucdane	silelit vi act (7, mich. F.a.	1970			. 9 101	ac re	: 174		<i>)</i> 14.	
	Calhoun	Located In:	Corner Code ##									
C	larendon Twp.						TE OF					
1. Put	olic Land Survey	T 4 S R 5 W	G-9		CALHOUN COUNTY Recorded							
		T R T R					******		•			
		T R				22 SI	EP 95	10:0	3 A.	Ħ.		
2. Pro	perty Controlling	S T R				Aus	NE B.	ומחנג	AUDE	D		
	Section	S T R			r						2	
	scellaneous			Registe	er of l	Deeds	Stam	p &	File	Num	ber	
Pro	perty in Sec.	S R										
4. Lot	: No , R	lecorded Plat			A R	СБ	E F	F G	H	l J	ĸ	L Ma
					ΪŤ	ŤŤ	Ti	Ť	- - 	\sqcap	Ì	
		•		3	6- 	5- 	1-1	1	-3— 	2	十	17
П	anderstelle T			3		11	11		<u> </u>			
	rederick J.	in a field curvey on Sont	cembor 15 10 05	,		8-	٦į		-10 	- ;		-12
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the									Ţ			13-
						Τï						
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5									丌		\top	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				fa ,	19	1 50	7-1	,				
Court of Law; established, re-established, monumented, re-monumented, recovered, found as				as 10		29	26	Ψ.	Ţ			25
expressed below:					30-	Ĩ					\top	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						32	32					36-
	On this certificate.			12 13	3,		Ţ		_ <u></u>	Lï		Ĭ_
A. De	scription of original i	monument and accessories and	d/or subsequent restoration:	,~				_				
		Sections 21, 22, 27 8		ange 5 W	Vest	•						
	riginal Governm 'N 22° E 5 1ks	ent Survey, December 1	1825: Ironwood 6" S 4	10-1/2°	W 1	4 1k	3.; I	[ror	OOWE	xd		
R.	Clark, 1826:	Maple 14" N 68° W 19 1	lks.; Maple 12" S 31°	E 22 1k	s.							
D. 53	Davis, 11/81: 3.2'; 12" Hicko	S.E. Corner Section ory N 75° E 113.6'.	21; R.R. spike center	cline ro	oad;	40"	W. ()ak	S 4	15°	E	

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. spike in centerline intersections of roads.

One of above references was found.

REMONUMENTATION

FEB 2 2 1996

COMMISSION



Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced R.R. spike with county issue Bernsten marker in monument box and is accepted as a careful and faithful reestablishment of the position of the original corner.

In centerline intersection of roads.
Nail & spotter in 48" Oak S 50° E 52.40'.
Nail & spotter in Power Pole S 42° E 83.68'.
Top center telephone stanchion N 65° E 48.25'.
Nail & spotter in 8" Hickory S 30° W 75.85'.

LIBER 1822 PAGE 40

Signed by frederick J. Cutcher Date	-September 19, 1995
	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975