## CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

APPROVED
Date 164. 26 12/05 CALHOUN COUNTY
REMONIMENTATION

nr	con	ስድ	18	in

or comera in											
Calhoun (County) Clarendon Twp.	Located In:	Corner Code ##									
. Public Land Survey	T <u>4 S</u> R <u>5</u> T <u> </u>				S	CALH		CHIGA OUNTY ED			
:. Property Controlling in Section	T R S T R S T R	<del>-</del>	_		22	SEP	95 10	:04 A	.H.		
Miscellaneous Property in Sec.	S T R		Re	gister o	f Pek	ANNE de S	B. NO E81197		ER DETE	gber	•
					в с	D E	E F	G H	l J	ĸ	L N
5. Private Claims				2 3	6	- 5	4	3-		!	_ _
Frederick J.	in a field survey on S	September 18 19	95	4		- 8	<b> 9</b>	10-		1-	12
o hereby certify that under req 1 lines 1 and 2 above were in	uirements of P.A. 74, Michiga conformance with regulatio	in P.A. of 1970, the corner points ons and rules therefore as requ Department of the Interior, Bure	mentioned uired in the	6	8	-17	-16-	15		4	-13-
fanagement or by a decree of a bove were in conformance wit	a Court of Law and/or that the h the rules of the Michigan B	corner points mentioned in line oard of Land Surveyors or by a life, re-monumented, recovered,	es 3, 4 and 5 Decree of a	8	9	20	21	22	2	3	_24
xpressed below:  IOTE: Not more than 4 co on this certificate.	orners, all in the same to	wn and range, may be reco	orded	11 12	30	29	-2'8- -33-	27-	0 3	6	_25 
•		es and/or subsequent restor		13		1		1_1			

Corner common to Sections 26, 27, 34 & 35, Town 4 South, Range 5 West.

Original Government Survey, December 1825: W. Oak 14" N 46° E 27 lks.; W. Oak 14" S 63-1/2° E 50 lks.

T.P.J., June 1978: centerline road; fence East; Twin 10" Elder N 50° W 48.55'; Twin 14" Basswood S 30° W 101.15'.

. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2"x18" iron rod in monument box set by Calhoun County Road Commission in the 1980's 1' East of centerline N/S road. Fence line to East.

One of above references was found.

PEMONUMENTATION

FEB 2 2 1996

COMMISSION



. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1/2"x18" iron rod with county issue Bernsten marker in monument box and is accepted as a careful and faithful reestablishment of the position of the original corner.

1' East of centerline N/S road.

Fence line to East.

Cherry 20" S 30° W 53.94'

Basswood 18" S 23° W 65.70'.

Basswood 8" N 75° E 27.52'.

Basswood 8" S 72° E 28.38'.

LIBER 1822 PAGE 45

igned by Auderick J. Cutcher	DateSeptember 19, 1995
Frederick J. Cutcher urveyor's Michigan License No. <u>24592</u>	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971