APPROVED

Date 18 1999 CALHOUN COUNTY

pec **CALHOUN COUNTY REMONUMENTATION**

STATE OF MICHIGAN CALLOR COUNTY

CALHOUN Located In: Corner Code # AND S. 1881 AND S. LISER 2154 PARE 422 LISER 2154 PARE		R RECORDATION CERTIFIC	
TERONSHATEMP 1. Problic Land Survey TAS_RBW TREATH TO THE PROBLEM STATE AND THE SURVEY SERVICE AND THE SURVEY S	i mig tvoquit	ement of Act 74, Wich. P.A. 1	· ·
TEROUSHATUP. 1. Public Land Survey T4S R6 W K9 TR R SURVEY 8 I. R SCHOOL 3. Miscellaneous S T R REDUCNIMENTATION 3. Miscellaneous S T R REDUCNIMENTATION 3. Miscellaneous S T R REDUCNIMENTATION 4. Lot No. Recarded Plat SECTION 5. Private Claims 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 5. Private Claims 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that under requirements of FA 74. Michigan PA of 1970, the corner points mentioned in lines 1 1. Finderick J. Cacher sale that	CALHOUN Located In: C	Corner Code #	ANNE II MIGI AMICO
2. Property Controlling S T R SURVEY 8. 3. Miscellaneous S T R SEMICINITIMENTATION 3. Miscellaneous S T R SEMICINITIMENTATION 4. Lot No. Recorded Plat SECTION 5. Private Claims 1. Finderick J. Cutcher in a field servey on August 17 19 99 on hereby abits the under requirement of PA 74. Modalay PA of 1970, the conner points mentioned in lines 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			CLERK - REGISTER OF MEDS
A Lot No	TR TR 		LIBER 2154 PAGE 422
4. Lot No	in Section S T R R 3. Miscellaneous S T R	EMONUMENTATION	Pacietar of Daade Stomp & Ella Neimba
S. Private Claims A. B. C. D. B. F. G. H. I. V. K. L. I. Fiederick. J. Cutcher she but under replacements of FA. 74, Michigan P.A. of 1970, the corner polds mentioned in lines 1 of survey instructions of the United States Department of the Interfer. Bureau of Land Management of of survey instructions of the United States Department of the Interfer. Bureau of Land Management of of survey instructions of the United States Department of the Interfer. Bureau of Land Management of of survey instructions of the United States Department of the Interfer. Bureau of Land Management of of survey instructions of the United States Department of the Interfer. Bureau of Land Management of of survey instructions of the United States Department of the Interfer. Bureau of Land Management of of survey instructions of the United States Department of the Interfer. Oct. 1826. Robert Clark, Jr.: W. Oak 12" N. 48 1/2" W. 131 lks; W. Oak 16" S. 56" E. 16 lks. Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S. 68" W. 98 lks; Sugar Maple 8" N. 58 1/4" W. 75 lks. Witness Card, (no date, no name): Tile; W. oak 12" N. 48 1/2" W. 131; W. Oak 16" S. 56" E. 16; W. Oak 10" S. 68" W. 98; Sugar Maple 8" N. 58 1/4" W. 75 Witness Card, 777/52, G. Karns: 3/4" iron pin; 28" oak S. 69" W. 65.65; 24" Maple N. 57" W. 49 20; 24" Maple N. 25" W. 29 20; 26" Maple N. 54" E. 43.35; B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns withesses remain. C. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns withesses remain. C. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns withesses remain. C. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" ir	Property in Sec. S TR	MAR 1 3 2000	KoSister of pages Organia & Life (Affiliance
5. Private Claims I, Frederick J, Cutcher In a field survey on August 17 19.99 do hereby slate that under requirements of P.A. 74, Middigan P.A. of 1970, the corner politis meritioned in lines 1 19.11	4. Lot No, Recorded Plat	SECTION	ABCDEFGHTJEL
I, Erodeick J. Cutcher In a field survey on August 17. 19 99 do hereby self-bill under respirements of P.N. 34, Michigan P.A. of 1970, the corner polits mentioned in lines 1 of survey instructions of the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the United States begartness of the Notice of States in the States in the States of the Notice of States in the States in the States in the States of States in the S	5. Private Claims		
I. Frederick J. Culcher In: a field survey on August 17 In 99 do hereby shalt but under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and ruise therefore as regulared in the current manual of survey instructions of the United States bepartment of the Intellect. Bureau of Land Management or bottom of the United States bepartment of the Intellect. Bureau of Land Management or Conformance with the rules of the Michigan Board of Land Surveyors in lines 3.4 and 5 stores were in Conformance with the rules of the Michigan Board of Land Surveyors in lines 3.4 and 5 stores were in Land Surveyors in lines 3.4 and 5 stores were in Land Surveyors in lines 3.4 and 5 stores were in Land Surveyors in lines 3.4 and 5 stores were in Land Surveyors in lines 3.4 and 5 stores were in lines 3.4 and 5 stores were in Land Surveyors in lines 3.4 and 5 stores were in lines 5.4 and 5	. •		3
state that under requirements of PA. 74. Michigan PA. of 1870, the corner points mentioned in lines 1 of survey instruments conformance with regulations and rules therefore as required in the current manual of that the corner of survey instruments conformance with the rules of the Michigan Board of Land Surveyors as required in the current manual of that the corner points mentioned in lines 3, 4 and 5 anagament in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; and restricted, monumented, recovered, found as expressed below. NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: SLO, 1826, Robert Clark, Jr.: W. Oak 12" N. 48 1/2" W. 131 liks; W. Oak 16" S. 56" E. 16 liks. Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S. 68" W. 98 liks; Sugar Maple 8" N. 58 1/4" W. 75 liks. Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2" W. 131; W. Oak 16" S. 66" E. 16; W. Oak 10" S. 88" W. 98, Sugar Maple 8" N. 58 1/4" W. 75 liks. Witness Card, 77/f62, G. Karns: 3/4" iron pin; 28" oak S. 69" W. 65.65"; 24" Maple N. 57" W. 49.20"; 24" Maple N. 25" W. 29.20"; 26" Maple N. 54" E. 43.35. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 16" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2 N. of centerline T Drive South, Nail & spotter 36" Maple N. 68" E. 43.64", nail & spotter 30" Oak S. 77" W. 88 77", nail & spotter 36" Oak S. 72" W. 65.10", nail & spotter 36" Oak S. 72" W. 65.10", nail & spotter power p	Frederick Cutcher in a field aureur on Aure		
of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a focate of 3 count of Law and of right the corner points mentioned in lines 3, 4 and 5 above were in occupants with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law. A Description of Count of Law Count o	state that under requirements of P.A. 74, Michigan P.A. of 1970, the	corner points mentioned in lines 1	
A. Description of original monument and accessories and/or subsequent restoration: GLO, 1826, Robert Clark, Jr.; W. Oak 12" N. 48 1/2" W. 131 lks; W. Oak 16" S 56" E 16 lks. Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S. 68" W. 96 lks; Sugar Maple 8" N. 58 1/4" W. 75 lks. Witness Card (no dale, no name): Tile; W. oak 12" N. 48 1/2" W. 131; W. Oak 16" S 56" E 16; W. Oak 10" S. 68" W. 98 lks; Sugar Maple 8" N. 58 1/4" W. 75 lks. Witness Card, 777/62, G. Karns: 3/4" fron pin; 28" oak S. 69" W. 65.65"; 24" Maple N. 57" W. 49.20"; 24" Maple N. 25" W. 29.20"; 26" Maple N. 54" E 43.35". B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuale locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2" N. of centerline T Drive South, Nail & spotter 36" Maple N. 58" E 43.64", nail & spotter 30" Oak S. 72" W. 65.10", nail & spotter pwr. pole S. 20" E 84.55", nail & spotter 24" Wahrut S 60" 102.0"; top cen. conc. post S. 45" E. Signed by Audulation S. 24592 Signed by Audulation S. 24592 Date 8/18/99 Surveyor's Michigan License No 24592 24592 Date 8/18/99 Surveyor's Michigan License No 24592 Postero Augusto S of State Surveyor's Michigan License No 24592 Postero Augusto S of State Surveyor's Michigan License No 24592 Date 8/18/99 Surveyor's Michigan License No 24592 Postero Augusto S of State Surveyor's Michigan License No 24592 Postero Augusto S of State Surveyor's Michigan License No 24592 Postero Surveyor's Michigan License No 24592	of survey instructions of the United States Department of the Interior by a decree of a Court of Law and for that the corner points mentions	or, Bureau of Land Management or	
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: GLO, 1826, Robert Clark, Jr.; W. Oak 12" N. 48 1/2" W. 131 lks; W. Oak 16" S 56° E. 16 lks. Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S, 68° W. 96 lks; Sugar Maple 8" N. 58 1/4" W. 75 lks. Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2" W. 131; W. Oak 16" S, 56° E. 16; W. Oak 10" S, 68° W. 96; Sugar Maple 8" N. 58 1/4" W. 75. Witness Card, 7/7/62, G. Karns: 3/4" iron pin; 28" oak S, 69° W. 65,65°; 24" Maple N. 57° W. 49,20°; 24" Maple N. 25° W. 29,20°; 26" Maple N. 54° E. 43,35. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuale locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the hest available evidence of the position of the original corner. 2" N. of centerline T Drive South; Nall & spotter 36" Maple N. 58° E. 43,64°; nail & spotter 30" Oak S, 77° W. 88,77°; nail & spotter 36" Oak S, 72° W. 65,10°; nail & spotter 36" Maple N. 58° E. 43,64°; nail & spotter 24" Walnut S 60° 102.0°; top cen. conc. post S, 45° E. Signed by Author Maple N. 58° E. 43,64°; nail & spotter 24" Walnut S 60° 102.0°; top cen. conc. post S, 45° E. PROFESSIONAL 18" PROFESSIONAL SURVIVINE N. M. 12, 18" RESISSIONAL	conformance with the rules of the Michigan Board of Land Surveyors	or by a Decree of a Court of Law	
A Description of original monument and accessories and/or subsequent restoration: GLO, 1826, Robert Clark, Jr.: W. Oak 12" N. 48 1/2" W. 131 lks; W. Oak 16" S. 56" E. 16 lks. Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S. 68" W. 98 lks; Sugar Maple 8" N. 58 1/4" W. 75 lks. Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2" W. 131; W. Oak 16" S. 56" E. 16; W. Oak 10" S. 68" W. 98; Sugar Maple 8" N. 58 1/4" W. 75 Witness Card, 7/7/62, G. Karns: 3/4" iron pin; 28" oak S. 69" W. 65.65'; 24" Maple N. 57" W. 49.20'; 24" Maple N. 25" W. 29.20'; 26" Maple N. 54" E. 43.35'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2" N. of centerline T Drive South; Nail & spotter 36" Maple N. 58" E. 43.64'; nail & spotter 30" Oak S. 77" W. 88.77'; nail & spotter 36" Oak S. 72" W. 65.10'; nail & spotter pwr. pole S. 20" E. 84.55; pajl & spotter 24" Walnut S 60" 102.0'; top cen. conc. post S. 45" E. 43.92'. Signed by Audulation Surveyor's Michigan License No. 24592 24592 24592 24592 APPROVED BY MICHOMA STATE BOWD OF PROFESSOMAL SURVEYORS, JAM. 28, 1878 REMSED JAM. 188 REMSE	NOTE: Not more than 2 corners, all in the same town and ran	ge, may be recorded	
A Description of original monument and accessories and/or subsequent restoration: GLO, 1826, Robert Clark, Jr.: W. Oak 12" N. 48 1/2" W. 131 lks; W. Oak 16" S 56" E. 16 lks. Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S. 68" W. 98 lks; Sugar Maple 6" N. 58 1/4" W. 75 lks. Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2" W. 131; W. Oak 16" S. 56" E. 16; W. Oak 10" S. 68" W. 98; Sugar Maple 8" N. 58 1/4" W. 75. Witness Card, 77/762, G. Karns: 3/4" iron pin; 28" oak S. 69" W. 65.65'; 24" Maple N. 57" W. 49.20'; 24" Maple N. 25" W. 29.20'; 26" Maple N. 54" E. 43.35'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuale locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2 N. of centerline T Drive South; Nail & spotter 36" Maple N. 58" E. 43.64"; nail & spotter 30" Oak S. 77" W. 88.77"; nail & spotter 36" Oak S. 72" W. 65.10'; nail & spotter pwr. pole S. 20" E. 84.55; nail & spotter 24" Walnut S. 60" 102.0'; top cen. conc. post S. 45" E. Signed by Additional Additional Corner and accessories and the provision of the second of professional surveyors, July 24562 Signed by Additional Additional Corner and accessories and the provision of the second of professional surveyors, July 24562 Signed by Additional Additional Corner and accessories and the provision with the position of the second of professional surveyors, July 24562 Pages 100 M Approved by Michael State Bowe Of Professional Surveyors, July 24562 Pages 24562			
Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S. 68° W. 98 lks; Sugar Maple 8" N. 58 1/4° W. 75 lks. Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2° W. 131; W. Oak 16" S. 56° E. 16; W. Oak 10" S. 68° W. 98, Sugar Maple 8" N. 58 1/4° W. 75. Witness Card, 7/7/62, G. Karns: 3/4" iron pin; 28" oak S. 69" W. 65.65'; 24" Maple N. 57° W. 49.20'; 24" Maple N. 25° W. 29.20'; 26" Maple N. 54° E. 43.35'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2 N. of centerlins T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10'; nail & spotter pwr. pole S. 20" E 84.55; nail & Spotter 24" Walnut S 60° 102.0'; top cen. conc. post S. 45° E. Signed by Audus August Augu	A. Description of original monument and accessories and/or	subsequent restoration:	
Resurvey, 1891, James M. Gifford: Found stake and stones; W. Oak 10" S. 68° W. 98 lks; Sugar Maple 8" N. 58 1/4° W. 75 lks. Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2° W. 131; W. Oak 16" S. 56° E. 16; W. Oak 10" S. 68° W. 98, Sugar Maple 8" N. 58 1/4° W. 75. Witness Card, 7/7/62, G. Karns: 3/4" iron pin; 28" oak S. 69" W. 65.65'; 24" Maple N. 57° W. 49.20'; 24" Maple N. 25° W. 29.20'; 26" Maple N. 54° E. 43.35'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2 N. of centerlins T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10'; nail & spotter pwr. pole S. 20" E 84.55; nail & Spotter 24" Walnut S 60° 102.0'; top cen. conc. post S. 45° E. Signed by Audus August Augu	GLO, 1826, Robert Clark, Jr.: W. Oak 12" N. 48 1/2° W. 131	lks; W. Oak 16" S 56° E. 16 lks.	
Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2° W. 131; W. Oak 16" S. 56° E. 16; W. Oak 10" S. 88° W. 98; Sugar Maple 8" N. 58 1/4° W. 75. Witness Card, 7/7/62, G. Karns: 3/4" iron pin; 28" oak S. 69° W. 65.65'; 24" Maple N. 57° W. 49.20'; 24" Maple N. 25° W. 29.20'; 26" Maple N. 54° E. 43.35'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2" N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10'; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60° 102.0"; top cen. conc. post S. 45° E. OF MICHOEN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28.19 REVISED MAY 14.19 EXESSIONAL SURVEYORS, JAN. 28.19 REVISED MAY 14.19 REVISED MAY 14.		•	ar Manie 8" N. 58 1/4° W. 75 lbe
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South, Nail & spotter 36" Maple N. 58° E. 43.64", nail & spotter 30" Oak S. 77° W. 88.77", nail & spotter 36" Oak S. 72° W. 65.10", nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut \$ 60° 102.0"; top cen. conc. post S. 45° E. 43.92'. Of Microsoft Approved by Michigan License No. 24592 PROFESSIONAL SURVEYORS, JAIL 28.19 REVISED MAY 14.19	Witness Card (no date, no name): Tile; W. oak 12" N. 48 1/2°	•	•
Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10"; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0"; top cen. conc. post S. 45° E. 43.92'. Signed by Audauid A. Cathar G. Technology of the processional surveyors, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED	Witness Card, 7/7/62, G. Karns: 3/4" iron pin; 28" oak S. 69° Maple N. 54° E. 43.35'.	W. 65.65'; 24" Maple N. 57° W. 4	9.20'; 24" Maple N. 25° W. 29.20'; 26"
Found 3/4" x 18" iron over hollow clay tile. Two of Karns witnesses remain. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10"; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0"; top cen. conc. post S. 45° E. 43.92'. Signed by Audauid A. Cathar G. Technology of the processional surveyors, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28. 19 REVISED MAY PROVED	t e	T.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10"; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0"; top cen. conc. post S. 45° E. 43.92'. Signed by Jackson Jackson Date 8/18/99 Surveyor's Michigan License No. 24592 Date 8/18/99 Date 8/18/99 Bernsed MAPPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 19 REVISED MAY 14,19 REVISED MAY 14,19	B. Description of corner evidence found and/or method applie	ed in restoring or reestablishing c	orner:
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64'; nail & spotter 30" Oak S. 77° W. 88.77'; nail & spotter 36" Oak S. 72° W. 65.10'; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0'; top cen. conc. post S. 45° E. 43.92'. Of Michigan License No. 24592 24592 Date 8/18/99 REVISED MAY 14.19	Found 3/4" x 18" iron over hollow clay tile.		
Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10"; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0"; top cen. conc. post S. 45° E. 43.92". Of Michigan License No. 24592 Professional Surveyor's Michigan License No. 24592 Professional Surveyor Michigan State Board of Professional Surveyors, Jan. 28, 19 Revised May 14,199 Revised May 14,199 Revised Jun., 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner.	Two of Karns witnesses remain.		• • • • • • • • • • • • • • • • • • • •
Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10"; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0"; top cen. conc. post S. 45° E. 43.92". Of Michigan License No. 24592 Professional Surveyor's Michigan License No. 24592 Professional Surveyor Michigan State Board of Professional Surveyors, Jan. 28, 19 Revised May 14,199 Revised May 14,199 Revised Jun., 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner.		•	
Replaced 3/4" x 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner. 2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64"; nail & spotter 30" Oak S. 77° W. 88.77"; nail & spotter 36" Oak S. 72° W. 65.10"; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0"; top cen. conc. post S. 45° E. 43.92". Of Michigan License No. 24592 Professional Surveyor's Michigan License No. 24592 Professional Surveyor Michigan State Board of Professional Surveyors, Jan. 28, 19 Revised May 14,199 Revised May 14,199 Revised Jun., 18" iron with Berntsen in monument box over tile and is accepted as the best available evidence of the position of the original corner.			
2' N. of centerline T Drive South; Nail & spotter 36" Maple N. 58° E. 43.64'; nail & spotter 30" Oak S. 77° W. 88.77'; nail & spotter 36" Oak S. 72° W. 65.10'; nail & spotter pwr. pole S. 20° E. 84.55; nail & spotter 24" Walnut S 60°102.0'; top cen. conc. post S. 45° E. 43.92'. Signed by Andrew Correction of Microscopic Science (Conc. post S. 45° E. 43.92) Surveyor's Michigan License No. 24592 Date 8/18/99 Surveyor's Michigan License No. 24592 Form Approved by Michigan State Board of Professional Surveyors, Jan. 28, 19 Revised May 14,19 Revised May 14,19 Revised May 14,19 Revised Jan., 19	C. Description of monument for corner and accessories established	olished to perpetuate locating the	position of the corner:
Signed by Author Cuther Professional Surveyor's Michigan License No. 24592 Signed by Approved by Michigan State Board of Professional Surveyors, Jan. 28, 19 Revised May 14,19 Revised May 14,19 Revised May 14,19	Replaced 3/4" \times 18" iron with Berntsen in monument box over original corner.	tile and is accepted as the best a	vailable evidence of the position of the
Signed by Auducia Cutata Surveyor's Michigan License No. 24592 Surveyor's Michigan License No. 24592 OFERSION APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 19 REVISED MAY 14,19 REVISED JAN., 19	43.92'.	nail & spotter 24" Walnut S 60°1	ak S. 77° W. 88.77'; nail & spotter 36" 02.0'; top cen. conc. post S. 45° E.
DEDARCE ART AR	Signed by Frederick J. Cutcher	EDERICK J. CUTCHER OFESSIONAL BURVEYOR LO. 24592	