

## MAR 3 0 1999

## APPROVED

Date\_12-9-98 RRC CALHOUN COUNTY PENADMILIMENTATION.

## CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

STATE OF MICHIGAN CALHOUN COUNTY RECURDED

roi comers in		
Calhoun	Located In:	

Corner Code #

D-5

15 DEC 1998 3:34:27 PM

(County) **Burlington Township** 1. Public Land Survey

T45 R7W

ANNE B. NORLANDER CLERK - REGISTER OF DEEDS

2. Property Controlling in Section

LIBER 2087 PAGE 926

3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat
5. Private Claims	
_	<del></del>

in a field survey on November 30, 19 98 do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	À_	B	C	Ð	8	F	G	H	I	J	K	L M
-	i	1	1	1	1	Τ	Τ-	T	Τ	T	Ţ	7-1
2	-	6	-	<u> </u>		4-		- ģ		ź	<del></del>	i
3	<u> </u>	-	$\vdash$	-	_	-	_	-	-	<u> </u>	_	
4	$\vdash$	<del> </del>	$\vdash$	8	<del> -</del>	9	-	10-	1	1	-	12
5	-	╁	-	•	-	<del> </del>	-	-				-
6	-:	   		7		6-	-	15	1	   4	<del> </del>	13
7		╄-	┼		-	-	-		·			
8	1	ا وا	-;	;0		   1	-	22	L-2	3		4-
9		<del> </del> -		-			.	<del> </del> -				
10	3	0	-2	9	2	8	<del> </del> ;	 2 <sup> </sup> 7	2	6	2	5-
11						-	-	-				
12	3	1	—3	2	—3	3—		34	<b>—</b> 3	5	-3	6
13	Щ.	L	L	L	L	<u> </u>	<u> </u>	1	L		<u> </u>	

A. Description of original monument and accessories and/or subsequent restoration:

GLO Robert Clark, 1826;

7" W. ash 8" Maple

S 87° W

N 73° W

96 links 441/2 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1' x 1' rectangular stone, 2' long, standing upright with a hole in the top, at the intersection of fences North, South, East and West. Accepted location of stone for corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced stone with standard Calhoun County Remonumentation monument (Berntsen monument with Carsonite marker) and is accepted as the best available evidence of the position of the original corner.

Nail and tag in 16" Maple Nail and tag in 14" Maple Nail and tag in 12" Oak Nail and tag in 20" Oak

S 15\* W

79.60

East N 10° W

40.85

N 80° W

37.15 75 92

Date December 9, 1998

CRANE ¥ NO. 29243 ... OF THE LAND SURVEY INTERNATIONAL LAND SURVEY INTERNATION **SURVEYOR** 

OF MICHES

William K. Crane, P.S.

Surveyor's Michigan License No.\_ 29243