SURVEY & REMONUMENTATION

FEB 1 9 1998

Liber 00003 Page 0146

Coloredo.	TO A CONTROL
SEU	TION

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 COUNTY OF CASS COUNTY REMONUMENTATION

For corners in CASS	Located In:	Corner Code #	12-26-1997 12:00:56	20 /0 20 /0
(County)			15-70-1531 17-00-00	
1. Public Land Survey VOLINIA TWP.	T <u>5S</u> R <u>14W</u>	H-1	Ann L. Simmons REGISTER OF DEEDS	
•	T R T R T R			
2. Property Controlling in Section	S T R S T R			n Aoc Chairr
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File N	umber
4. Lot No, Re	ecorded Plat		ABCDEFGHIJ	K L M

•	•			
I, DALE L. KESLER	, in a field survey on	JULY 23	, 19 <u>97</u>	_do
hereby state that under requirement	its of P.A. 74, Michigan P.A.	of 1970, the corn	er points mentio	ned
in lines 1 and 2 above were in co	nformance with regulations	and rules therefor	e as required in	the
current manual of survey instruction				
Management or by a decree of a	Court of Law and /or that the	corner points ma	ntioned in lines :	3, 4
and 5 above were in conformance				
Decree of a Court of Law; establis	shed, re-established, monum	ented, recovered,	found as expres	ssed
below:	•			
			•	

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- *1827 WILLIAM BROOKFIELD. SET QUARTER POST, 6" HAGWOOD N 74 1/4 DEGREES E 25 LKS., 10" HAGWOOD N 15 DEGREES W 27 LKS.
- *JUNE 9, 1900 GEORGE MUTCHLER, COUNTY SURVEYOR. STAKE AND STONE REMAINS OF BOTH WITNESS TREES. RE-WITNESS: 8" SUGAR S 58 ½ DEGREES W 82 ½ LKS., 5" BUTTERNUT n 53 ½ DEGREES W 65 ½ LKS.
- *APRIL 11, 1972 & MARCH 29, 1985 SW SURVEY & ENGINEERING CO., USED CORNER, FENCE LINE 5' W OF CORNER.
- *JUNE 7, 1974 DENNIS MIDDLETON. FOUND OLD PIPE EXTREME NORTH EDGE OF TRAVEL, FOUND R.O.W. IRON 33' NORTH, SET R.O.W. 33' SOUTH ON QUARTER LINE.
- *APRIL 6, 1994 ROBERT R. CARR, L.C.R.C., LIBER 1, PG 353. IRON IN MONUMENT BOX, 24" OAK S/SE 60.10' TO CENTERLINE, 36" MAPLE SW 33.20' TO CENTERLINE.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" IRON PIPE IN MONUMENT BOX. THE ACCESSORIES OF THE L.C.R.C. RECORDED IN LIBER 1, PAGE 353 DATED JULY 1, 1974, AND THE ACCESSORIES OF THE L.C.R.C. RECORDED IN LIBER 2, PG 332 DATED APRIL 12, 1994, VERIFY LOCATION OF CORNER. ACCEPTED 3/4" IRON PIPE AS BEST EVIDENCE OF CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET HARRISON MARKER IN MONUMENT BOX IN PLACE OF 3/4" IRON PIPE AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

NAIL & TAG W'LY SIDE 30" OAK S 10 DEGREES E 33.26'
NAIL & TAG E'LY SIDE 6" CHERRY N 35 DEGREES E 34.62'
FACE OF R.R. POST S 48 DEGREES E 63.48'

RIGHT OF WAY IRON NORTH 33.00' RIGHT OF WAY IRON SOUTH 33.00'

CORNER IS A COMMON CORNER WITH VAN BUREN COUNTY



3 4 5

11

13

Signed by	Dale	Ckur	** ORIBINATED EST	Date 12/1	1/97
• . —	chigan License No	38117			4