LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 CASS COUNTY REMONUMENTATION For corners in Located in: Corner Code # CASS STATE OF MICHIGAN (County) COUNTY OF CASS 1. Public Land Survey T 5S R 15W <u>M-7</u> Recorded SE Cor. Sec. 13 12-21-1999 13:26:09 R چ in Accord Ann L. Simmons Ratified 2. Property Controlling REGISTER OF DEEDS in Section S Τ 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. . Recorded Plat 6. Private Claims 1 2 3 DALE L. KESLER in a field survey on November 2 , 19<u>99</u> hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 4 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 5 current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 6 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a 7 Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed 8 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 11 Description of original monument and accessories and/or subsequent restoration: 12 March 20, 1827 William Brookfield set corner. April 24, 1830 John Mullett - intersected West boundary at post. Witnesses: 20" White Oak N 25 Deg. W 176 links; 24" White Oak S 52 Deg. W 208 links. May 15, 1872 C.J. Brandt - Lost - Established - 6" Yellow Oak N 6 1/4 Deg. E 288 links. June 12, 1978 Robert Prestine - LCRC Liber 2, Page 62 - standard monument over stone. Witnesses: 30 d spike in S. Side 36" Oak, N 38 Deg. E 41.40'; Bolt on Top tele. Pedestal S 32 Deg E 54.60'. 30d spike in S. Side 48" oak N 88 Deg. W 80.95' Face fence cor. post N 86 Deg. W 24.6' November 7, 1985 Wightman-Peirce. Found standard monument. January 1993 Wightman-Peirce. Found standard monument. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found standard monument set by Prestine dated June 9, 1978, and recorded in Liber 2, Page 62. Prestine found stone from a survey done by J.C. Bradt dated May 1872 and set a standard monument above stone. Accepted standard monument as best evidence of the original corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C. Set 3/4" x 24" iron pipe with aluminum cap in a monument box in place of standard monument and is accepted as a careful and faithful perpetuation of the original corner.

Nail in 48" Oak N 40 Deg E 41.76'
Nail in 18" Cherry W 39.63'
C/L RR Tie Line Post N 75 Deg. W 26.4'
C/L Tele Riser S 40 Deg. E 53.85'

Signed by

Signed by

Date Dec. 20, 1999

Surveyor's Michigan License No._

PF

Signed by

38117

4

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Dec. 20, 1999

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

FEB 2 4 2000

PRELITY &

SECTION