LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_	T. N. E. W.	
2. PROPERTY CONTROLL- ING IN SECTION —	4 ,T. 6 S., R. 13 W.	<u>#7,</u> #6
		Misc. Point
4. LOT NO , R	ECORDED PLAT	
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentione field survey on restored as expressed below of survey instructions of the court of law. Furtherm 19	ed in lines 1 and 2 above (identified in lines 1 and 2 above (identified), established, wand in conformance with regulation and in conformance with regulation and the United States Department of the core, that the corner points meroe, found, recovered, restored, established.	that under requirements of P.A.74, Michigan P.A. of 1970, ified with circles on index code diagram—over) were, in a re-established, monumented, re-monumented, recovered or ations and rules therefore as required in the current manual me Interior, Bureau of Land Management or by a decree of a nationed in lines 3, 4 and 5 above were, in a field survey on tablished or re-established as expressed below and in congistration for Land Surveyors or, by a Decree of a Court of
A. Description of original	monument and accessories and/o	or subsequent restoration:
Set 3/4" Iron Pipe 3/4 Iron Pipe	Sec. line and centerline from Survey by T. A. Smir. P. at bend in line y Pole	th 1943 N. 60 W. 146.84' Trans. Pole Spike & Tag
#7 Set 4" x 36" con	c. mon. with alum 0.00' N. of E. 1/4 corne	lied in restoring or re-establishing corner: #6 Found 1/2" Iron Pipe r With Pipe cap from Survey by Michiana Surveyors.
#7 Att = 3611 Comp. m		#6 1/2" Iron Pipe S. 40 W. 27.60' Sq. Fence Post Spike and Tag N. 23 W. 44.00' 36" Cherry Spike and Tag S. 86 E. 109.30' 14" Cherry Spike and Tag
SIGNED BY		DATE
SURVEYOR'S MICHIGAN	REGISTRATION NO	(SEAL)
FOR STATE AND UNITED		
SIGNED BY	CHIEF OF SURVEY PARTY	DATE
APPROVED AND SIGNED BY.		
	MICHIGAN REGISTERED LAND	(SEAL)