Liber 00003 Page 0158

FEB 1 9 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 SECTION

,	CASS CO	JN I T REMONUMENTATION	SIMIE OF LITCUIDARA	10
For corners in		Canad Cada #	COUNTY OF CASS	55.7 15.7
CASS	_ Located In:	Corner Code #	Recorded	
(County)				<u> </u>
1. Public Land Survey NEWBERG TOWNSHIP	T <u>6S</u> R <u>13W</u>	M-7	12-26-1997 12:03:45	Pest Group
MEANDERG TOWNSTIII	T R	}	Ann L. Simmons	- ë S
	T R		REGISTER OF DEEDS	8 8
	TR			2 6
2. Property Controlling	S T R			Ratified by Per In Accordance
in Section	S TR			2 = 2
3. Miscellaneous	S R		_	
Property in Sec.	S		Register of Deeds Stamp & F	He Number
4. Lot No, Rece	orded Plat		ABCDEFGHI	JKL
5. Private Claims				
			2 6 5 4 4 3 +	-2-1-
I,DALE L. KESLER	in a field survey on	SEPT 22 19 97 do	3	
I, <u>DALE L. KESLER</u> , in a field survey on <u>SEPT. 22</u> , 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			4 - 7 8 9 10	-1,11,2-
in lines 1 and 2 above were in o	conformance with regulations and	rules therefore as required in the	5	
_	•	ent of the Interior, Bureau of Land	6 18 17 16 15	-14-13-
Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed			7 1 1 1 1 1 1	Î
below:	•		8 -19 -20 -21 -22 -	_2324
NOTE: Not more than 2 comes	s, all in the same town and range,	may be recorded	9	
on this certificate.			10 30 29 28 27	-25-
			11	
 Description of original mo 	nument and accessories and/or	subsequent restoration:	12 31 32 33 34	3536
* lune 25 1929 Government	survey notes from Calvin Britta	in indicate set post per To	13	
	llow oak 10", North 5 degrees,			
degrees W 3.00 ch.	a o , o g g.			
*April 20, 1954 Survey by Jay 13.86' N of NW corner, Section		ound at NE corner, Section 24,		
		e iron found at SW corner, Sectio	n 18, T6S, R12W, Fabius Towns	ship. St.
Joseph County, Michigan. Ca	ss corner North 13.94 - RR spi	ke on County line.		
*April 25, 1975 Survey by	H.D. Peirce indicates marke	er found at SE corner of Section	ın 13.	
3. Description of corner evid	dence found and/or method app	olied in restoring or reestablishing	comer:	
Found 1/2" iron in monumen	t box below the asphalt. M	easured South 13.94 feet to 1	the Northwest corner of Section	on 19,
Г6S, R12W, St. Joseph Co	unty, Michigan. Accepted	1/2" iron as best evidence of o	corner.	

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 2' iron pipe with aluminum cap in place of ½" iron rod and is accepted as the best available evidence of the position of the original corner.

Southwesterly corner pole barm N 80 degrees 48' E 129.50'

Power pole w/ok pail N side S 48 degrees 50' F 43.53' CANAL OF MICH

Power pole w/pk nail N side S 48 degrees 50' E 43.53' Power pole w/pk nail S side S 64 degrees 16' W 61.85'

CL of 10" pine tree N 74 degrees 55' E 71.50'

PAUS ONNI OSS Bigned by Date <u>12/4/97</u> Burveyor's Michigan License No. 38117

DALEL

KELLER

LAND SURVEYOR