JAN 2 1 1999

SECTION

## CASS COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF CASS Recorded

12-22-1998 15:39:33

Ann L. Simmons REGISTER OF DEEDS In Accordar

Ratified by Peer Group Register of Deeds Stamp & File Number


1. Public Land Surve	/ T <u>6S</u> T T T	R <u>16W</u> R R	_A-4
<ol><li>Property Controllin in Section</li></ol>	g S T S T	R R	And the second s
<ol><li>Miscellaneous Property in Sec.</li></ol>	s T	_R _R	

I, Alan Bartlett in a field survey on November 13.1998 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(NOT SET IN ORIGINAL GOVERNMENT SURVEY)



Liber 00003 Pase 0184

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This Corner not set in original government survey. This corner reestablished using best available evidence on township line at ½ mile split. This corner approved by the Cass County Remonumentation Peer Group of Surveyors on October 21,1998.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Concrete Monument with Cass County remonumentation cap 1.5' East of North/ South fence and 23' South of East West Fence.

Witnesses

Set Nail and Flasher in E. side of 6" Hickory 1.62 South Set Nail and Flasher in E Side of 22" Tree 22.92 **N15E** 32.07 Set Nail and Flasher in SE side 18" Poplar N50F Set Nail and Flasher in NE side 10" Oak 44.09 S60E

This position not established by original government survey. This Monument is accepted as the best available evidence of the position of the corner.

Surveyor's Michigan License No. 35988

