LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in						
Cass County		Located In:				Corner Code ##
1.	Public Land Survey		Ţ	7S	R 13	W M-5 .M-4
			T		R	- · · · · · · · · · · · · · · · · · · ·
			T		R	
			T		R	
2.	Property Controlling	S	T		R	<u></u>
	in Section	S	T		R .	
3.	Miscellaneous	S.	T		R	

Register of Deeds Stamp & File Number


4. Lot No. , Recorded Plat

5. Private Claims ...

Property in Sec.

October 0 Donald L. Bissell in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

M-5 SE Cor. Sec. 12

10" W. Oak - S12 3/4°W - 48 Lks.

15" W. Oak - N 9°W - 47 Lks.

M-4 E 1/4 Cor Sec. 12

9" W. Oak 1/4 Section Corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-5 SE Cor. Sec. 12

Found Old Rotted Stake and Rotted Remains of

Trees at Location of Original

Witnesses.

Set 4" x 36" Conc. Mon. w/Alum.

Cap in Place of Rotted

Stake. In Old North-South Fence Line.

M-4 E 1/4 Cor. Sec. 12

Set 1/2" Rod in Center of 26" Hollow Stump. Original

1/4 Corner. Stump Deteriorated

and Fall Apart.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5 SE Cor. Sec. 12

N29°E - 27.30' - 6" Hickory S17°E - 21.06' - 4" Hickory N69°W - 31.63' - 6" W. Oak N36°W - 20.60' - 20" R. Oak S4°W - 76.50' - 4" Conc. Mon.

M-4 E 1/4 Cor. Sec. 12

N5^OE - 42.41' - 22" Sassafrass S78^OE - 7.45' - Power Pole

\$400 E - 39.23' - R. Oak

South - 20.80' - 5" Cherry, in North Trunk

Surveyor's Michigan License No. ___



LAND SURVEYORS, JAN 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983