STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			Chippewa	COUNTY
		Τ.	41-42N	R <u>3-4E</u>
DESCRIPTION OF CORNER S	ec. Cor. common to Secs. 6-1-	36-31	, also a to	wnship corner.
CORNER MONUMENT 1" pipe	with 4" Aluminum Cap.			
DATE MONUMENT PLACED AND W	ITNESSED 8-23-71			
WITNESSES TO CORNER	12" Soft Maple (S36 NBT) N3	2 ⁰ W_1	.6.31	
NSec1	10" Y. Birch (S31 NBT) N42° Found trees marked some year 15" Y. Birch South 40.2° AND 13" Soft Maple S72° E 7.6°			n Surveyor:
CIRCLE CORNER REGISTERED				
DESCRIPTION IN DETAIL AS TO	THOM CODNED HAS LOCATED AND	TOENT	TITITO AD DE	CTARER

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a 2" Iron Pipe, set by unknown surveyor. Found the noted trees marked as well as numerous blazes in vicinity. Checked distance North to lake.

SURVEYOR'S SEAL

SIGNED

Billy V. Buckles.

REGISTERED LAND SURVEYOR

DATE 9-22-71

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing