


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Chippewa COUNTY
T 41-42N R 3E

DESCRIPTION OF CORNER 1/2 Cor. bet. Secs. 1-36
CORNER MONUMENT Concrete monument with brass plate,
"Chippewa County Corner"
DATE MONUMENT PLACED AND WITNESSED 8-23-71

WITNESSES TO CORNER..... 10" Cedar (1/2 NBT) N11°E 4.7'



12" Cedar (1/2 NBT) S34°E 11.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by the Chippewa County Surveyor's Office. Found no evidence of the original witnesses in proper position. There are numerous cedar stumps in vicinity. Corner lies 8' East of a trail road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE 9-22-71

REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68