

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Chippewa COUNTY


T 41-42N R 3E

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 2-3-34-35

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 8-23-71

WITNESSES TO CORNER..... 8" Cedar (S3 NBT) West 8.4'



8" Cedar (S35 NBT) N39°E 25.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established, on a N.- S. blazed line and on a line between known corners to East and West. Found no evidence of original witnesses or corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Billy D. Buckler

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

9-22-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68