

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Chippewa COUNTY
T 41-42N R 3E

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 4-5-32-33

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5-13-71

WITNESSES TO CORNER..... 9" Cedar (S4 NBT) S22°E 21.7'



11" Cedar (S5 NBT) S65°W 46.6'

12" Soft Maple (S33 NBT) N63°E 22.5'

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a 1" x 22" Iron Bolt, set by unknown surveyor. Found several blazed trees at corner but could identify no original evidence. Distance East to swamp edge checks well.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 9-22-71
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68