STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Chippewa	0	COUNTY
	Τ.	41N	R _3	BE
DESCRIPTION OF CORNER Sec. Cor. common to Secs. 2-3-3	<u>9-11</u>	·		
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap				
DATE MONUMENT PLACED AND WITNESSED 8-24-71				
WITNESSES TO CORNER 16" Hard Maple (S3 NBT) N100	W 54	•01		
10" Hard Maple (S10 NBT) S71	.°₩ 4]	1.1*		
AND				
CIRCLE CORNER REGISTERED	<u> </u>			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established on line and by single proportionate measure, between Sec. Corners; one mile East and one mile West. Found no evidence at corner, which falls 40° North of an open area. Did find a few blazes, a long line, to North of this corner.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

E 0_22_77

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing