

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 41 .. NR 5 East ..

Chippewa
Drummond Island ..

COUNTY

DESCRIPTION OF CORNER .. Sec. Cor. 1-2-11-12 ..

DESCRIPTION OF CORNER MONUMENT .. 1" Pipe with 4" Brass Cap ..

WITNESSES TO CORNER .. 9" Cedar (S1 NBT) N80°E 33 lks. ..

.. 9" Cedar (S2 NBT) N61°W 35 lks. ..

.. 8" Cedar (S11 NBT) S60°W 30 lks. ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced cor. from Cedar B.T. bearing N16°W 16 lks. tree down and in poor condition. Found two old Cedar posts in place. Cor. lies 93 lks. south and about 3 chs. east of cor. set by Beaudry, Co. Surveyor. Cor. found and wit., 7/31/58 with W. Lehmann, D.F.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 7/30/59
REGISTERED LAND SURVEYOR