

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T41 & 42 NR - 6 E . .

----- Chippewa ----- COUNTY
(Drummond Island)
DESCRIPTION OF CORNER 1/4 Section Corner between Sections 31 and 6 . . .
DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . .
WITNESSES TO CORNER 8" Cedar S 15° W 16 links . . .
8" Cedar S 68° W 18 1/2 links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced 1/4 Corner from one Cedar B.T. in good condition (down).

Corner shown to us by Wesley Lehmann, District Forester.

Corner placed and witnessed February 28, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler. DATE 3/19/56
REGISTERED LAND SURVEYOR