

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 41 NR 6 East

Chippewa

Drummond Island COUNTY

DESCRIPTION OF CORNER Wit. cor. to meander cor. between secs: 7-18 on west side of  
of Pat's Lake

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Cedar (WC NBT) S20<sup>o</sup>W 24 Lks.

10" Cedar (WC NBT) S22<sup>o</sup>W 39 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Found Cedar B.T. bearing N78<sup>o</sup>W 33 Lks., tree down and broken off.

blazes and scribe marks plain. Set wit. cor. 25 lks. west of

meander cor. and witnessed wit. cor. Cor. placed and wit. 7/30/59.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 7/30/59  
REGISTERED LAND SURVEYOR