## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 41 N. R. 6	L-1, K-2
2. PROPERTY CONTROLL- ING IN SECTION-	,T	
3. MISCELLANEOUS PROPERTY IN SECTION	,T	
4. LOT NO, RECORDED PLAT,		
5. PRIVATE CAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- -1 1/4 cor. on North side of sec. 1. Wood Post, Cedar 9", N15°E, 22 lks. & Cedar 12", N21°W, 20 lks.
- -2 West 1/4 cor. of sec. 1. Wood Post, Cedar 6", N45°E, 22 lks. & Aspen 6", S46°E, 6 lks.
  - B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- -1 Corner set from 2 ObT'S, Cedar 9" N15°E, 22 lks. & Cedar 12", N21°W, 20 lks. Loth trees are down but faces and notch plain.
- -2 Set M.F.(.L. between the NW and SW sec. cors. of sec. 1.
  - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- -1 D.N.R. Moument. New Bearings:

K-2 D.N.R. Monument. New Bearings:

12" Cedar, NO4"W, 34.0' 8" Cedar, East, 8.1' 7" Cedar, S32°E, 24.0' c" Cedar, NE, 21.0' 10" W. Eirch, N29°E, 27.8' 4" Spruce, S50°W, 9.7' 6" Balsam, N22°W, 43.0' 10" Spruce, S18°E, 21.15'

SIGNED BY Lavid B. Baffitt

DATE 8-3-82

SURVEYOR'S MICHIGAN REGISTRATION NO.\_\_\_

(SEA

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

.... DATE