

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
CHIPPEWA CO. 3 CORNERS.

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 41 N. XX R. 6 E. XX	I-1, F-3
2. PROPERTY CONTROLLING IN SECTION 9 _____	T. 41 N. XX R. 6 E. XX	2
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 9-15 & 10-15, 19 87, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- I-1 N.E. Section Corner of Section 3. This corner was set by Dean C. DeLaMater in 1950 Bearings 6" Balsam, S59°W, 6 lks. & 5" Cedar, N68°W, 11 lks. & 5" Cedar, N27°W, 22 lks.
- F-3 North 1/4 Corner of Section 9. OBT'S: Spruce 10, N84°E, 16 lks. & Birch 6, N18°W, 68 lks.
- 2 East 1/16 Corner of Section 9 on North side. Not prev. set.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- I-1 Re-witt. this corner at a found 4" Sq. Stake set by Dean C. DeLaMater RLS #5778 in 1950.
- F-3 Corner set by single proportionate measure between N.E. and N.W. Corners of Section 9. Proportionate distance west to rock ledge fits original distance.
- 2 Corner set M.P.O.L. between N.E. Section Corner and North 1/4 Corner of Section 9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR MONUMENTS SET AT ALL THREE CORNERS.

- | | | | | | |
|-----|-------------------------|-----|------------------------|---|------------------------|
| I-1 | 12" Cedar, N28°W, 14.4' | F-3 | 8" Cedar, S47°W, 69.1' | 2 | 6" Cedar, S35°E, 16.7' |
| | 8" Cedar, N28°E, 17.7' | | 8" Cedar, N8°E, 51.0' | | 6" Cedar, S7°W, 16.55' |
| | 6" Cedar, East, 8.3' | | 8" Cedar, N70°E, 47.8' | | 8" Cedar, S72°W, 9.15' |
| | 6" Cedar, S13°E, 8.3' | | 6" Cedar, N85°E, 27.3' | | 8" Cedar, N45°E, 8.65' |

SIGNED BY Gerald L. Wiggins
Gerald L. Wiggins

DATE 5-18-87

SURVEYOR'S MICHIGAN REGISTRATION NO. 23521

FOR STATE AND UNITED STATES AGENCIES:

