LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

CHIPPEWA CO. # CORNERS

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
	I. PUBLIC LAND SURVEY	T. 41 XX. R. 6 XX	1-6	
	2. PROPERTY CONTROLL-	5_ ,T <u>41_y8</u> , R <u>6_y8</u> ,	7. 16-14	
	3. MISCELLANEOUS PROPERTY IN SECTION			
		,	·	
	4. LOT NO, RE	CORDED PLAT		
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
	I, Gerald L. Wiggins	, do hereby e	ertify that under requirements of	P.A. 74, Michigan P.A. of 1970.
	re-established, monumented, re and rules therefore as required Bureau of Land Management of and 5 above were, in a field sur	Ines 1 and 2 above were, in a e-monumented, recovered or re in the current manual of surver by a decree of a court of law, vey on	field survey on 5-24 stored as expressed below and it is instructions of the United State Furthermore, that the corner 19, found, recovered, restor Michigan State Board of Registration	, 19_88, established, in conformance with regulations sites Department of the Interior, points mentioned in lines 3, 4 and established or recentablished.
I-6	A. Description of original mon East 1/4 Corner of Sc	ument and accessories and/or section 15. 0.B.T.'S.	subsequent restoration: Cedar 6, S62°W, 6 Lks.	. 6 Tamarack 8, N49°E, 14 Lki
7	North 1/16 Corner on	east side of Section	15. Not previously set	:.
16-1	4. Meander Corner bet	veen Sections 15 and 1	4. 0.B.T.'S. Spruce 1 Cedar,	0, N42°E, 24 lks. 8 6, S62°E, 39 lks.
1-6	Corner set record a	listance from the N.E.	ed in restoring or re-establishing Corner of Section 15 an een Sections 14 and 15.	
7	Corner set M.P.O.L.	between the N.E. Corn	ner and the East 1/4 Co	rner of Section 15.
16-1	4 Corner set at found Huron. Also there	1/2" re-rod. This po is an old road running	osition fits with origi g North from this iron.	nal meanders of Lake
1-6	Description of monument fo DNR Monument 12" Cedar, N63°E, 16. 8" Cedar, N4°W, 15. 8" Cedar, N62°W, 10. 12" Cedar, S78°W, 29.	4' 10" Cedar, N 8' 8" W. Birch, S 1' 12" Cedar. S8'	\$19 ° E, 32.05' 6' °W, 37.8 5' 8'	osition of the corner: -rod W/Plastic RLS Cap "Cedar, S53°E, 9.7' "Cedar, East, 10.9' "Cedar, N27°E, 10.75' "Cedar, N62°E, 12.3'
	SIGNED BY GOTALE, WILLIAM REC	,,	DATE 6-30-88	GERALD L. WIGGINS LAND SURVEYOR L. No.
F	OR STATE AND UNITED ST	ATES AGENCIES:	The second control of	CAND SUPPLIES
s	IGNED BY	CHIEF OF SURVEY PARTY	DATE	
٨	PPROVED AND SIGNED BY		DATE	 -