

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 7. E.

Drummond Island

----- Chippewa ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 15, 16, 21, 22

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

24" W. Pipe - N 67 E - 41 Links

12" Cedar - S 32 W - 28 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by W. A. Lehmann, District Forester, of Sault Ste. Marie. One original B.T. still in place, in good condition.

Corner was placed and witnessed October 5, 1953.

SURVEYORS SEAL

SIGNED *John C. [Signature]*
REGISTERED LAND SURVEYOR

DATE 1/15/54