

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 7. E.

Drummond Island

----- Chippewa ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 14 & 15 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER -----

12" Cedar - N 25 W - 23 Links -----

8" Cedar - N 70 E - 41 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by W. A. Lehmann, District Forester, of Sault Ste. Marie. One original B.T. still in place, down, in fair condition.

Corner was placed and witnessed October 6, 1953.

SURVEYORS SEAL

SIGNED John C. DeLoater
REGISTERED LAND SURVEYOR

DATE 1/26/54