

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 NR. 7 E.
T. 42 NR. 7 E.
Drummond Island

----- Chippewa ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5, 6, 31, 32 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER -----

----- 10" W. Birch - N 12 W - 15 Links -----

----- 10" W. Pine - N 87 W - 55 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Two original B.F.'s still in place, in poor condition.

Corner was placed and witnessed October 9, 1953.

SURVEYORS SEAL

SIGNED *John C. DeLoe* DATE 1/26/54
REGISTERED LAND SURVEYOR