

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 2 E.

Chippewa

COUNTY

(Drummond Island)

DESCRIPTION OF CORNER Meander Corner between Sections 9 and 16

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 15" Red Pine S 65° E 50 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set M. C. on East shore of Dickinson Lake, from two Cedar B.T.'s in excellent condition (growing).

Corner shown to us by Daniel Bonner, Assistant District Forester.

Corner placed and witnessed February 29, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 3/19/56