

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 41N N.R. 7E


Chippewa COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. Secs. 12-13.

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-5-70

WITNESSES TO CORNER..... 12" Cedar (15 RBT) 24° E 21.4'



12" Cedar (15 RBT) 150° W 34.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old squared. Cedar post, placed by unknown surveyor.

Found no evidence of original corner but position did check well with other corners in this area.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
REGISTERED LAND SURVEYOR DATE 8-26-70