


MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 41N N.R. 7E

Chippewa COUNTY

DESCRIPTION OF CORNER Sec Cor. common to Secs. 11-12-13-14

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5-5-70

WITNESSES TO CORNER..... 12" Cedar (S 12 NBT) 129°E 1.4'

15" Cedar (S 13 NBT) S53°E 27.1'

13" Cedar (S 14 NBT) S51°W 14.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.  
This corner replaced at an old squared cedar post, set by, unknown surveyor.  
Found no positive evidence of original corner or witnesses.

Placed location poster 7.00 chains north of corner, on a trail.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 5-27-70  
REGISTERED LAND SURVEYOR