

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41N N. R. 7E


Chippewa COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 11-14.

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-5-70

WITNESSES TO CORNER..... 13" Hard Maple (¼S 11/14 NBT) N20°W 16.9'



13" Hard Maple (¼S NBT) S75°E 24.6'

10" Cedar (¼S 11/14 NBT) S19°W 21.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old cedar post, placed by unknown surveyor.
Found no evidence of the original corner or witnesses.

Placed location poster on a trail, 100' South of corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8-27-70
REGISTERED LAND SURVEYOR