

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Chippewa Co.

1 Corner

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. _____ N. S., R. _____ E. W.		
2. PROPERTY CONTROLLING IN SECTION <u>26</u> , T. <u>41</u> N. S., R. <u>7</u> E. W.		Meander Corner South of I-9 Called I-9A
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-23, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

I-9A Meander Corner bet. Sections 26-27, on Lake Huron, set by John Mullett, D.S. in 1845.
Bearings were: Tamarack 8", N31°W, 1.10 chains & Cedar 7", N13°E, 1.06 chains.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:


I-9A Found a pipe in concrete, with two more recent witnesses, apparently set by Miller, R.L.S. in 1951, while surveying a record plat. Found original witnesses, the Cedar still green.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-9A Recorded corner as found. No new witnesses or monument necessary.

SIGNED BY Billy D. Buckler
Billy D. Buckler
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

DATE 5-5-81



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY
APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____